



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8233G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	CUT	499.90	499.90
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER GRILLE LH	CUT	85.10	85.10
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	77.00	-
1	FRONT BUMPER SIDE BRACKET LH	NECESSARY	82.30	82.30
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	945.30	-
1	FRONT FENDER HYBRID LH	NECESSARY	86.50	86.50
	LESS 25% DISCOUNT		-449.53	-193.95
			1,348.57	581.85
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH.		800.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
			1,400.00	1,200.00
	GRAND TOTAL		2,748.57	1,781.85
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,781.85

Report Ref No. NS/INC22001602/Vty3n2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.