



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9008U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER EMBLEM	NECESSARY	26.60	26.60
1	FRONT FENDER RH	BENT	588.50	588.50
1	FRONT PILLAR GARNISH RH	MISSING	75.00	75.00
1	RH SIDE ROCKER GARNISH	DEFORMED	290.00	290.00
1	FRONT DOOR RH	BENT	1,797.20	1,797.20
1	FRONT DOOR WING MIRROR RH	NOT NECESSARY	1,391.70	-
1	MOULDING ASSY-W/LINE FRT	DEFORMED	110.10	110.10
	LESS 20% DISCOUNT		-855.82	-577.48
			3,423.28	2,309.92
<u>SPECIAL NETT ITEMS</u>				
1	FRONT DOOR COMFORT STICKER (SN)	NECESSARY	75.00	75.00
			75.00	75.00
<u>LABOUR</u>				
	PANEL BEATING.		700.00	525.00
	SPRAY PAINTING CHARGE.		750.00	600.00
	REMOVE/REFIX DOOR PARTS.		120.00	60.00
	CHECK WIRING.		60.00	30.00
			1,630.00	1,215.00
GRAND TOTAL			5,128.28	3,599.92
RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,599.92

Report Ref No. NS/INC22001604/Tvy3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.