

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1197Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED	459.40	459.40
1	REAR BUMPER SIDE BRACKET RH	NECESSARY	55.80	55.80
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
1	REAR BUMPER CENTRE MOULDING	SCRATCHED	451.25	451.25
1	REAR BUMPER REFLECTOR RH	SCRATCHED	41.45	41.45
2	NUMBER PLATE LAMP LH/RH @\$42.65	SERVICEABLE	85.30	-
1	REAR FOG LAMP	SERVICEABLE	201.50	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-342.30	-205.98
			1,369.20	823.92
	NETT ITEMS			
1	REAR NUMBER PLATE W/HOLDER (N)	CRACKED	55.00	55.00
1	REAR REVERSE SENSOR (N)	CUT	180.00	180.00
	LESS 10% DISCOUNT		-23.50	-23.50
			211.50	211.50
	SPECIAL NETT ITEMS			
2	REAR FENDER ADVERTISEMENT LH/RH (SN)	NECESSARY	200.00	200.00
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			250.00	250.00
	<u>LABOUR</u>			
	PANEL BEATING.		500.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK LIGHTING AND WIRING.		60.00	20.00
	TUFF KOTE.		60.00	20.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	20.00
			980.00	660.00
	GRAND TOTAL		2,810.70	1,945.42

Report Ref No. NS/INC22001606/Vqy3n2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,550.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22001606/Vqy3n2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**