

ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396 Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To:

Pro-Tac Armada Pte Ltd

C/o:

160 Sin Ming Drive #05-20

Sin Ming AutoCity (S) 575722

Date of request: Date of inspection: 03.01.2022

08.12.2021

Date of report:

08.12.2021

Date of accident:

30.11.2021

Report No: AAS/2021/292

Claim type: Third Party Claim

Particulars of affected vehicle:

Registration no:

SNA6523Y -

Toyota Alphard (A)

Odometer:

9586 km

Make/Model:

Engine Capacity:

2493 cc 2AR2601527

Year of registration:

2021

Engine no:

Colour:

Pearl White

Chassis no:

AGH300363050

Condition of tires:

Front Left:

Make:

7mm

Make: Toyo

7mm Rear Left:

Toyo

Front Right:

7mm

Make:

Toyo

Rear Right: Make:

7mm Toyo

Type of road wheel:

Alloy

(The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork

Paintwork

Handbrake

Footbrake

Steering

: Good

: Good

: In order

: In order

: In order

: Nil Apparent engine modification

The Assignment

The inspection was conduct at M/s.

Lim Motor Pte Ltd

160 Sin Ming Drive #05-20

Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

Assessment

Repairer's estimate:

6,489.23

Revised estimate:

\$ 5,801.50

Recommended reserve:

\$ 4,650.00 (Lump sum)

Estimated normal duration of repairs: 4 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722 Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SNA6523Y

Report No: AAS/2021/292

W/O PREJUDICE

Point of impact

At the RHF portion.

General description of damages

The front bumper, front grille, RH headlamp, RHF fender, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Lim Motor Pte Ltd as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$5,801.50

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$4,650.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of $\underline{4}$ working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a 'Without Prejudice' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes $\underline{50}$ photographs.

Your Faithfully Absolute Appraisal Services Pte Ltd

Nicky Seah Automobile Appraiser MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396 Email: absolute.app.svcs@gmail.com

| Vehicle No: SNA6523Y | | | | | Re | Report No: AAS/2021/292 | | |
|--|--|------|--------------------------------|-------------------|-----------|-------------------------|------------------|--|
| App | raisement Schedule | | | | | | | |
| S/N | Parts Description | Qty | Condition | | Re | pairer's Est | Revised Est | |
| 1 | Front bumper | 1. | Dented/Cut | | \$ | 1,833.40 | \$ 1,833.40 | |
| 2 | Front bumper chrome LH/RHSUC | 2 | Broken/Necessary | \$ 220.6 | 0 \$ | 441.20 | \$ 441.20 270. | |
| 3 | Front bumper side grille RH | 1 | Loop Cracked | | \$ | 156.70 | \$ 156.70 | |
| 4 | Front bumper fog lamp RH | 1 | Refit | | . \$ | 340.00 | - | |
| 5 | Front bumper bracket RH | 1 | Cracked | | 3\$ | 115.00 | \$ 115.00 | |
| 6 | Front bumper absorber | 1 | Refit | | \$ | 90.30 | | |
| 7 | Radiator grille | 1 | Grazed/Cut | | \$ | 865.40 | \$ 865.40/ | |
| 8 | Radiator grille emblem | 1 | Necessary | | \$ | 105.90 | \$ 105.90/ | |
| 9 | Headlamp RH | 1 | Grazed/Cut | | \$ | 2,970.50 | \$ 2,970.50~ | |
| 10 | Headlamp chrome RH | 1 | Grazed | | \$ | 133.90 | \$ 133.90 | |
| 11 | RHF fender | | Distorted/Repair | | | - | - | |
| | | | | Total: | \$ | 7,052.30 | \$ 6,622.00 (788 | |
| | | | | -25% | \$ | 1,763.08 | \$ 1,655.50 | |
| | | | | List total: | \$ | 5,289.23 | \$ 4,966.50 3591 | |
| | | | | Mot to tall | | 4,447 | 3325. | |
| 1 | Front bumper clips | 1set | Necessary | | \$ | 50.00 | \$ 30.00 20 | |
| | | | | Special nett tota | al: \$ | 50.00 | \$ 30.00 @ | |
| | | | | Parts Total: | \$ | 5,339.23 | \$ 4,996.50 | |
| /N | Labour Description | | | | Re | epairer's Est | Revised Est | |
| 1 | Check lightings & wirings. | | | | \$ | 50.00 | \$ 30.00 20 | |
| 2 Renew damaged parts. Panel beat, reform RHF fender. Re-align area. | | | | ign all affected | \$ | 500.00 | \$ 375.00 | |
| 3 | Spray painting on rear affected & | | \$ | 600.00 | \$ 400.00 | | | |
| | | | | Labour Total | \$ | 1,150.00 | \$ 805.00 | |
| | | | | Grand Total: | \$ | 6,489.23 | \$ 5,801.50 | |
| The | final adjusted lump sum amount | is | \$4,650.00 | | | | 257.11 | |
| Under normal circumstances the renair should be completed | | | | | | | 3202-10 | |
| Under normal circumstances, the repair should be completed within a reasonable period of 4 working days. | | | | | 37 | 17.48 | 3525.16 | |
| | | | | | -3 | , | | |
| | Photographs were taken at the tim | | | | - | | V . 1 . 1 N | |
| scl | aimer: This report is intended for the exclusive | | the address solely in relation | | | | | |
| | | | | | | | | |

liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.