

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001616/EVY3N2**Date:** 27/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00115672101		
Claimant Vehicle No :	SJP7938X	Insured Vehicle No :	GBG6366U		
Date of Loss:	09/02/2022	Nature of Claim:	TP	Claim No:	SNM22D201223/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP7938X		
Make & Model:	TOYOTA COROLLA, 1.5 AXIO (A)	Engine No:	1NZD252476
Reg. Date:	09/04/2009 (Man. Year: 2008)	Chassis No:	NZE1416103069
Colour:	Silver	Odometer:	147824 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,999.62	1,861.55	1,138.07	37.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,320.00	730.00	35.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,049.62	3,181.55	1,868.07	36.99
Approved Total (Overridden) (\$\$)		2,450.00		
(\$\$)	5,049.62	2,450.00	2,599.62	51.48
+ GST 7.00/7.00% (\$\$)	353.47	171.50	181.97	51.48
Nett Amount (\$\$)	5,403.09	2,621.50	2,781.59	51.48

INSPECTION

Date of Assignment:	18/02/2022		
Date Inspected:	24/02/2022	Inspected At:	15 FAN YONG ROAD SINGAPORE 629792 REPAIRER: MOVA AUTOMOTIVE PTE LTD
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2022)
Parts:	143	TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP7938X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	688.50 FL	*688.50 FL
2	2		*BOOT LID HINGE RH & LH (NPA)	Repair	0.00 FL	*- FL
3	1		*BOOT LID LOGO	Necessary	50.80 FL	*50.80 FL
4	1		*BOOT LID EMBLEM-AXIO	Necessary	44.70 FL	*44.70 FL
5	1		*BOOT LID EMBLEM-X	Necessary	36.60 FL	*36.60 FL
6	1		*BOOT LID GARNISH	Broken	252.80 FL	*252.80 FL
7	1		*BOOT LID LOCK	Not Necessary	94.50 FL	*- FL
8	1		*BOOT LID WEATHERSTRIP	Not Necessary	167.20 FL	*- FL
9	1		*REAR END PANEL	Repair	463.20 FL	*- FL
10	1		*TAILLAMP ASSY RH & LH (2 Pcs)	Cut (1 Pc only)	678.80 FL	*339.40 FL
11	1		*REAR BUMPER	Dented	424.20 FL	*424.20 FL
12	2		*REAR BUMPER BRACKET RH & LH	Not Necessary	374.80 FL	*- FL
13	2		*REAR BUMPER RETAONER RH & LH	Broken	348.40 FL	*348.40 FL
14	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*30.00 FL
15	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS
16	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,919.50	2,415.40
- List Item Discount on L Items 25.00/25.00% (S\$)	919.88	553.85
Total Parts (S\$)	2,999.62	1,861.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT/WELD REAR END PANEL,KNOCK AND STRAIGHTEN REAR BOOT MEMBERS,REMOVE AND REPLACE ACCIDENT DAMAGED PARTS,REALIGN ALL CONNECTION	New	800.00	500.00
2	SPRAY PAINT BOOT LID,REAR END PANEL,REAR BUMPER,SPARE WHEEL PANEL,REAR FENDERS	New	1,000.00	700.00
3	REMOVE AND REPLACE LUGGAGE COMPARTMENT INNER TRIM,GARNISH,COVERING	New	60.00	30.00
4	REMOVE AND REPLACE REVERSE SENSOR AND CHECK FUNCTION	New	50.00	30.00
5	TO APPLY SEAL ON WELDING JOINTS	New	80.00	30.00
6	RUST PROOF AFFECTED AREA	New	60.00	30.00
Gross Labour Cost (\$)			2,050.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >