



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 585D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	N/S FRONT FENDER (WCP)	BENT	210.00	210.00
1	N/S INNER FENDER COWLING (WCP)	NOT NECESSARY	85.00	-
1	N/S FRONT FENDER HYBRID EMBLEM (WCP)	NOT NECESSARY	25.00	-
1	N/S FRONT FENDER WIND DEFLECTOR (WCP)	NOT NECESSARY	35.00	-
1	N/S FRONT DOOR (WCP)	BUCKLED	450.00	450.00
1	N/S FRONT DOOR OUTER HANDLE (WCP)	CUT	140.00	140.00
1	N/S FRONT DOOR OUTER HANDLE EXTENSION (WCP)	CUT	30.00	18.00
1	N/S FRONT DOOR OUTER MOULDING (WCP)	NOT NECESSARY	40.00	-
1	N/S FRONT DOOR LOCK (WCP)	NOT NECESSARY	240.00	-
1	N/S FRONT DOOR POWER WINDOW MOTOR (WCP)	NOT NECESSARY	245.00	-
1	N/S FRONT DOOR POWER WINDOW REGULATOR (WCP)	NOT NECESSARY	75.00	-
1	N/S FRONT DOOR WEATHER STRIP (WCP)	NOT NECESSARY	60.00	-
1	N/S SIDE MIRROR COVER (WCP)	TO REPAIR SEE LABOUR	38.00	-
1	N/S SIDE MIRROR SIGNAL LAMP (WCP)	CRACKED	25.00	25.00
1	N/S REAR DOOR (WCP)	BUCKLED	420.00	420.00
1	N/S REAR DOOR OUTER MOULDING (WCP)	NOT NECESSARY	40.00	-
1	N/S REAR FENDER (WCP)	TO REPAIR SEE LABOUR	380.00	-
1	N/S REAR FENDER STICKER (WCP)	NOT NECESSARY	25.00	-
1	N/S REAR WHEEL CAP (WCP)	CUT	85.00	85.00
1	N/S REAR DOOR WEATHER STRIP (WCP)	NOT NECESSARY	60.00	-
	COST PLUS 10%		270.80	134.80
			2,978.80	1,482.80
<u>NETT ITEMS</u>				
1	N/S FENDER QUARTER GLASS PRIME (N)	NOT NECESSARY	80.00	-
1	N/S FENDER QUARTER GLASS SEALANT (N)	NOT NECESSARY	80.00	-
	COST PLUS 10%		16.00	-
			176.00	-

Report Ref No. CS6/AIS22001623/Gqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PUTTY AND SPRAY PAINTING ON LEFT SIDE OF THE AFFECTED PORTION.		1,200.00	800.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN ON LEFT SIDE OF THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF N/S SIDE MIRROR COVER AND N/S REAR FENDER.		850.00	500.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	120.00	-
	TO TRANSFER OF FRONT & REAR LEFT DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST. @\$160.00		320.00	100.00
	TO CHECK ELECTRICAL WIRING & LIGHTING CONCERNED.		80.00	20.00
			2,570.00	1,420.00
	GRAND TOTAL		5,724.80	2,902.80

RECOMMENDED COST OF REPAIRS			2,902.80
LESS EXCESS			-600.00
NETT LIABILITY			2,302.80

Report Ref No. CS6/AIS22001623/Gqf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.