

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001624/AEA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070160613
Claimant Vehicle No :	SLP5220Y	Insured Vehicle No :	SLG9212S
Date of Loss:	21/02/2022	Nature of Claim:	TP
		Claim No:	9014870620SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP5220Y	Engine No:	L15B4532278
Make & Model:	HONDA HR-V, 1.5 (A)	Chassis No:	JHMRU1810GX202279
Reg. Date:	08/06/2017 (Man. Year: 2017)	Odometer:	83324 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,054.96	3,444.16	4,610.80	57.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,930.00	810.00	29.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,794.96	5,374.16	5,420.80	50.22
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	10,794.96	4,300.00	6,494.96	60.17
+ GST 7.00/7.00% (S\$)	755.65	301.00	454.65	60.17
Nett Amount (S\$)	11,550.61	4,601.00	6,949.61	60.17
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,117.45		
Global Sum Settlement (S\$)		5,110.00		

INSPECTION

Date of Assignment:	21/02/2022	
Date Inspected:	21/02/2022 Inspected At:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	956.80 FL	*468.00 FL
2	2		*REAR BUMPER O/S & N/S TOP GARNISH	Repair	480.40 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
4	2		*REAR BUMPER SCREW CLIPS	Not Necessary	20.00 FS	*- FS
5	1		*REAR BUMPER O/S & N/S REFLECTOR	N/S Cut	470.80 FL	*151.00 FL
6	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	126.00 FL	*78.00 FL
7	2		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
8	1		*REAR END PANEL	Dented	611.90 FL	*415.00 FL
9	1		*REAR END PANEL INNER TRIM	Cracked	150.00 FL	*150.00 FL
10	2		*REAR O/S & N/S TAIL LAMP	Not Necessary	1,380.20 FL	*- FL
11	2		*REAR O/S & N/S TAIL LAMP CLIPS	Not Necessary	20.00 FS	*- FS
12	1		*REAR TAILGATE	Dented	1,378.00 FL	*878.00 FL
13	1		*REAR TAILGATE WEATHERSTRIP	Cut	365.00 FL	*188.00 FL
14	1		*REAR TAIL GATE H EMBLEM	Not Necessary	74.00 FL	*- FL
15	1		*REAR TAIL GATE I-VTEC EMBLEM	Necessary	95.00 FL	*95.00 FL
16	1		*REAR TAIL GATE HRV EMBLEM	Necessary	85.00 FL	*85.00 FL
17	1		*REAR TAILGATE INNER TRIM	Cracked	250.50 FL	*250.50 FL
18	1		*REAR TAILGATE INNER TRIM CLIPS (11 PCS)	Necessary	34.00 FS	*34.00 FS
19	1		*REAR TAIL GATE LOCK (UPPER)	Damaged	350.00 FL	*165.00 FL
20	1		*REAR TAIL GATE LOCK (LOWER)	Not Necessary	130.00 FL	*- FL
21	1		*REAR TAIL GATE O/S & N/S REFLECTOR	N/S Cracked	940.00 FL	*364.00 FL
22	1		*REAR WINDSCREEN MOULDING	Necessary	220.00 FL	*220.00 FL
23	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
24	1		*REAR BUZZER	Cracked	310.00 FL	*85.00 FL
25	1		*REAR SPARE WHEEL TANK PANEL	Repair	832.40 FL	*- FL
26	1		*REAR UNDERCOVER	Torn	295.20 FL	*295.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,955.20	4,221.70
- List Item Discount on L Items 20.00/20.00% (\$)	1,900.24	777.54
Total Parts (\$)	8,054.96	3,444.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	1,200.00	800.00
2	TO SPRAY PAINTING	New	1,000.00	800.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	140.00	120.00
4	TO REMOVE & RELACE REAR REVERSE SENSOR	New	50.00	50.00
5	TO REMOVE & REPLACE REAR TAIL-GATE FITINGS	New	80.00	80.00
6	TO RE-SET ELECTRICAL SYSTEM	New	120.00	0.00
7	TO CHECK WIRING	New	100.00	30.00
8	TO RE-SEAL ANTI -RUST	New	50.00	50.00
Gross Labour Cost (\$\$)			2,740.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >