

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CC3/AIG22001627/AQY3E2**Date:** 14/10/2022**REFERENCE**

Insured/Claimant:	LUO LINA	Policy No:	7210129271		
Date of Loss:	13/02/2022	Nature of Claim:	OD	Claim No:	0610325380SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNC4815H</b>		
Make & Model:	AUDI Q2, 1.5 TFSI S TRONIC (A)	Engine No:	DPCD27259
Reg. Date:	25/10/2021 (Man. Year: 2021)	Chassis No:	WAUZZZGA1MA033733
Colour:	White	Odometer:	7124 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$165,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,274.00	3,468.16	2,805.84	44.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,072.00	2,047.00	3,025.00	59.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,346.00</b>	<b>5,515.16</b>	<b>5,830.84</b>	<b>51.39</b>
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>(S\$)</b>	10,546.00	4,715.16	5,830.84	55.29
<b>+ GST 7.00/7.00% (S\$)</b>	738.22	330.06	408.16	55.29
<b>Nett Amount (S\$)</b>	<b>11,284.22</b>	<b>5,045.22</b>	<b>6,239.00</b>	<b>55.29</b>

**INSPECTION**

Date of Assignment:	18/02/2022		
Date Inspected:	18/02/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,290.00 FS	*1,090.40 FS
2	1		*REAR BUMPER ANTHRACITE TRIM-LH	Deformed	89.00 FS	*71.04 FS
3	1		*REAR BUMPER TRIM-LH	Deformed	60.00 FS	*47.92 FS
4	1		*SENSOR SUPPORT-LH OUTER	Not Necessary	25.00 FS	*- FS
5	1		*REAR LIGHT REFLECTOR-LH	Cut	34.00 FS	*26.48 FS
6	1		*REAR TAIL LIGHT-LH	Cracked	1,469.00 FS	*1,175.20 FS
7	1		*REAR TAIL LIGHT TRIM-LH	Not Necessary	34.00 FS	*- FS
8	1		*REAR BUMPER CARRIER	Not Necessary	615.00 FS	*- FS
9	1		*REAR BUMPER HOLDING STRAP	Not Necessary	15.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION-LH	Not Necessary	60.00 FS	*- FS
11	1		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
12	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
13	2		*REAR WHEEL ARCH COVER-LH/RH	Necessary	360.00 FS	*287.20 FS
14	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
15	1		*REAR BUMPER LOWER SPOILER (Supplementary)	Cut	927.00 FS	*741.20 FS
16	1		*REAR VENT TRIM - LH (Supplementary)	Deformed	36.00 FS	*28.72 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>6,274.00      3,468.16</b>
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REPAIR LHS TAIL LAMP PANEL (Supplementary)	New	800.00	250.00
6	TO RESPRAY LHS TAIL LAMP PANEL (Supplementary)	New	1,600.00	275.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,072.00</b>	<b>2,047.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >