

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22001632/AQY3E2**Date:** 09/11/2022**REFERENCE**

Insured/Claimant: INTERNATIONAL FIBRE RESOURCES PTE LTD

Policy No: 2100439266-06

Date of Loss: 16/02/2022

Nature of Claim: OD

Claim No: 7861298360SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKW9975B**

Make & Model: AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)

Engine No: CYG004888

Reg. Date: 24/11/2015 (Man. Year: 2015)

Chassis No: WAUZZZ4GXFN083339

Colour: Bronze

Odometer: 42678 km

Engine Capacity: 1798 cc

Market Value/New Car Price: S\$81,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45R18

Rear Tyre Size: 245/45R18

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	55,391.00	21,458.24	33,932.76	61.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	23,484.00	12,134.00	11,350.00	48.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	78,875.00	33,592.24	45,282.76	57.41
Approved Total (Overridden) (S\$)		25,900.00		
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	78,075.00	25,100.00	52,975.00	67.85
+ GST 7.00/7.00% (S\$)	5,465.25	1,757.00	3,708.25	67.85
Nett Amount (S\$)	83,540.25	26,857.00	56,683.25	67.85

INSPECTION

Date of Assignment: 21/02/2022

Date Inspected: 18/02/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	3,012.00 FS	*2,409.60 FS
2	1		*FRONT BUMPER GRILLE	Not Necessary	739.00 FS	*- FS
3	18		*LOCKING CLIP	Not Necessary	78.00 FS	*- FS
4	1		*FRONT BUMPER CHROME TRIM	Not Necessary	340.00 FS	*- FS
5	1		*FRONT BUMPER FIXING PARTS	Not Necessary	54.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	237.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Not Necessary	276.00 FS	*- FS
8	1		*RADIATOR GRILLE	Not Necessary	2,140.00 FS	*- FS
9	1		*RADIATOR GRILLE COVER	Not Necessary	41.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Cut	393.00 FS	*314.00 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE COVER-LH	Not Necessary	58.00 FS	*- FS
12	1		*FRONT WHEEL SPOILER-LH	Torn	294.00 FS	*234.80 FS
13	1		*LIFT CYLINDER CAP COVER	Not Necessary	64.00 FS	*- FS
14	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	265.00 FS	*- FS
15	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	927.00 FS	*- FS
16	1		*FRONT BUMPER GUIDE PIECE-LH	Distorted	42.00 FS	*33.12 FS
17	1		*FRONT BUMPER BRACE-LH	Not Necessary	34.00 FS	*- FS
18	1		*FRONT BUMPER TOP COVER	Torn	137.00 FS	*109.60 FS
19	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
20	1		*AIR COND STICKER	Necessary	34.00 FS	*26.96 FS
21	2		*FRONT PARKING AID SENSOR-INNER/OUTER	Not Necessary	488.00 FS	*- FS
22	1		*FRONT PARKING AID SENSOR SIDE	Not Necessary	244.00 FS	*- FS
23	6		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
24	1		*FRONT BUMPER WIRING	Not Necessary	642.00 FS	*- FS
25	1		*HORN-LH	Not Necessary	214.00 FS	*- FS
26	1		*HORN SUPPORT-LH	Not Necessary	53.00 FS	*- FS
27	1		*FRONT FENDER-LH	Distorted	1,560.00 FS	*1,248.00 FS
28	1		*FRONT FENDER ATTACHMENT PARTS	Necessary	107.00 FS	*85.60 FS
29	1		*FRONT FENDER STONE GUARD FILM-LH	Necessary	135.00 FS	*108.00 FS
30	1		*FRONT FENDER BRACE-LH	Distorted	107.00 FS	*85.60 FS
31	1		*FRONT FENDER CLOSING ELEMENT-LH	Distorted	60.00 FS	*47.28 FS
32	1		*FRONT FENDER SEAL-LH	Distorted	23.00 FS	*17.92 FS
33	1		*FRONT FENDER SEALING ELEMENT-LH	Distorted	45.00 FS	*35.36 FS
34	1		*FRONT WHEEL HOUSING LINER-LH	Deformed	310.00 FS	*248.00 FS
35	1		*FRONT FENDER STONE CHIP GUARD-LH	Not Necessary	82.00 FS	*- FS
36	1		*FRONT FENDER ADHESIVE TAPE	Necessary	59.00 FS	*47.20 FS
37	1		*FRONT FENDER TRIM BRACKET-LH	Not Necessary	19.00 FS	*- FS
38	1		*BONNET	Not Necessary	5,736.00 FS	*- FS
39	1		*BONNET ATTACHMENT PARTS	Not Necessary	186.00 FS	*- FS
40	1		*HEADLIGHT MOUNTING-LH	Smashed	132.00 FS	*105.20 FS
41	1		*HEADLIGHT MATRIX BEAM-LH	Smashed	13,172.00 FS	*10,537.60 FS
42	1		*SIGNAL LIGHT POWER MODULE	Not Necessary	611.00 FS	*- FS
43	1		*DIPPED BEAM POWER MODULE	Not Necessary	625.00 FS	*- FS
44	1		*HEADLIGHT MATRIX POWER MODULE	Not Necessary	2,121.00 FS	*- FS
45	1		*HEADLIGHT HOSE-LH	Not Necessary	40.00 FS	*- FS
46	1		*HEADLAMPS FAN-LH	Not Necessary	428.00 FS	*- FS
47	1		*HEADLIGHT ADJUSTMENT ELEMENT	Not Necessary	51.00 FS	*- FS
48	2		*SPACER	Not Necessary	92.00 FS	*- FS
49	1		*LIFT CYLINDER-LH	Not Necessary	259.00 FS	*- FS
50	1		*LIFT CYLINDER HOSE	Not Necessary	553.00 FS	*- FS
51	1		*LOCK CARRIER	Cracked	1,385.00 FS	*1,108.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	6		*RADIATOR COOLANT	Necessary	282.00 FS	*225.60 FS
53	1		*RADIATOR AIR GUIDE-LH	Not Necessary	86.00 FS	*- FS
54	1		*RADIATOR AIR GUIDE UPPER CENTER COVER	Not Necessary	32.00 FS	*- FS
55	1		*FRONT FENDER TOP SUPPORT-LH UPPER	Distorted	841.00 FS	*672.80 FS
56	1		*NOISE INSULATION PLATE-LH	Damaged	37.00 FS	*29.12 FS
57	1		*FRONT FENDER TOP SUPPORT-LOWER UPPER	Buckled	326.00 FS	*260.80 FS
58	1		*WATER DEFLECTOR STRIP-LH	Not Necessary	75.00 FS	*- FS
59	1		*ROOF CHROME MOULDING-LH	Not Necessary	571.00 FS	*- FS
60	1		*FRONT WINDOW SLOT SEAL TRIM STRIP-LH	Not Necessary	380.00 FS	*- FS
61	1		*ALUMINIUM RIM	Not Necessary	1,847.00 FS	*- FS
62	4		*RUBBER VALVE	Not Necessary	15.00 FS	*- FS
63	1		*WISHBONE LINK-LH	Bent	605.00 FS	*483.60 FS
64	1		*WISHBONE SUSPENSION GUIDE	Bent	1,095.00 FS	*876.00 FS
65	1		*FRONT UPPER ARM-LH FRONT	Not Necessary	605.00 FS	*- FS
66	1		*FRONT UPPER ARM-LH REAR	Not Necessary	605.00 FS	*- FS
67	1		*WHEEL BEARING HOUSING-LH	Not Necessary	1,256.00 FS	*- FS
68	1		*WISHBONE SWIVEL JOINT	Bent	191.00 FS	*152.80 FS
69	1		*WISHBONE WHEEL HUB	Damaged	518.00 FS	*414.40 FS
70	1		*WHEEL BEARING ASSEMBLY PARTS	Damaged	570.00 FS	*455.60 FS
71	1		*SUSPENSION FORKS-LH	Not Necessary	263.00 FS	*- FS
72	2		*COUPLING ROD	Not Necessary	258.00 FS	*- FS
73	1		*ANTI-ROLL BAR	Not Necessary	548.00 FS	*- FS
74	1		*GAS SHOCK ABSORBER	Not Necessary	628.00 FS	*- FS
75	1		*DRIVE SHAFT VELOCITY JOINT-LH	Not Necessary	3,239.00 FS	*- FS
76	1		*TRACK ROD	Bent	109.00 FS	*87.20 FS
77	1		*TIE ROD END-LH	Bent	195.00 FS	*155.60 FS
78	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
79	1		*ARYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
80	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
81	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
82	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
83	1		*SUNDRIES	Necessary	600.00 FS	*14.56 FS
84	1		*HEADLIGHT WASHER PIPE (Supplementary)	Torn	45.00 FS	*35.92 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	55,391.00	21,458.24
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR.HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER CHARGE AIR COOLER AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT PRESSURISE.VACCUM AND REGAS	New	1,700.00	1,700.00
4	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,800.00	2,800.00
5	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER	New	800.00	0.00
6	TO SETUP THE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR	New	2,400.00	0.00
7	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER,BONNET AND LHS HEADLIGHT.TO CUT OUT AND WELD LHS FRONT FENDER TOP SUPPORT TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	8,000.00	3,250.00
8	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER,BONNET,LHS FRONT FENDER TOP SUPPORT.LHS FRONT DOOR AND LHS UPPER A-PILLAR	New	6,000.00	2,750.00
9	TO RENEW LHS FRONT RIM.TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			23,484.00	12,134.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >