



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22001636/Avy3e2	
			Date: 28/03/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 6140J	Veh. Inspected	GBH 9310E
	Policy No.	D21MTPCVE000568	Coverage (\$)	0.00
	Claim No.	CMTD2200634/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	21/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTFAT35Y40K211743	Colour	WHITE
	Odometer	101565 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/70 R15C	YOKOHAMA	6 mm
	L/H Front Tyre	195/70 R15C	YOKOHAMA	6 mm
	R/H Rear Tyre	155 R12C	FALKEN	6 mm
	L/H Rear Tyre	155 R12C	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/02/2022	Inspection Date	21/02/2022
	Survey held at	1ST AUTO AUTOMOTIVE SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	