

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22001646/UVF3N2**Date:** 25/03/2022**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1000821662	
Claimant Vehicle No :	SMM1810A	Insured Vehicle No :	YN9697K	
Date of Loss:	18/02/2022	Nature of Claim:	TP	Claim No: 270051

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM1810A	Engine No:	L13B3931736
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Chassis No:	GK33417243
Reg. Date:	20/06/2019 (Man. Year: 2019)	Odometer:	47170 km
Colour:	Silver		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Firenza 7 mm	Rear Left Side:	Firenza 7 mm
Front Right Side:	Firenza 7 mm	Rear Right Side:	Firenza 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,807.04	636.16	7,170.88	91.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	1,000.00	2,410.00	70.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	11,217.04	1,636.16	9,580.88	85.41

INSPECTION

Date of Assignment:	21/02/2022		
Date Inspected:	21/02/2022	Inspected At:	Blk 15 Kaki Bukit Road 4, Bartley bIZ, #01-53
Estimated Period of Repair:	3.0 days		Repairer: Zoom Autowerks Pte Ltd

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2022)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM1810A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,150.00 FL	*- FL
2	1		*FRONT HEADLAMP-RH	Cracked	2,250.00 FL	*795.20 FL
3	1		*FRONT GRILLE	Not Necessary	395.00 FL	*- FL
4	1		*FRONT GRILLE CHROME	Not Necessary	260.00 FL	*- FL
5	1		*FRONT GRILLE LOGO	Not Necessary	55.00 FL	*- FL
6	1		*FRONT BUMPER	Not Necessary	1,050.50 FL	*- FL
7	1		*FRONT BUMPER BRACKET	Not Necessary	56.00 FL	*- FL
8	1		*FRONT BUMPER SIDE GRILLE	Not Necessary	115.00 FL	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	140.00 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	420.90 FL	*- FL
11	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	45.00 FL	*- FL
12	1		*FRONT FENDER-RH	Repair	580.00 FL	*- FL
13	1		*FRONT FENDER INNER SHIELD	Not Necessary	168.00 FL	*- FL
14	1		*FRONT WHEEL HUB	Not Necessary	138.30 FL	*- FL
15	1		*FRONT WHEEL BEARING	Not Necessary	168.30 FL	*- FL
16	1		*FRONT SHOCK ABSORBER	Not Necessary	420.30 FL	*- FL
17	1		*FRONT KNUCKLE ARM	Not Necessary	330.60 FL	*- FL
18	1		*FRONT LOWER ARM	Not Necessary	285.30 FL	*- FL
19	1		*FRONT TIE ROD	Not Necessary	105.60 FL	*- FL
20	1		*SET FRONT BUMPER CLIP	Not Necessary	50.00 FS	*- FS
21	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	50.00 FS	*- FS
22	1		*FRONT TYRE	Not Necessary	400.00 FS	*- FS
23	1		*FRONT WHEEL RIM-RH	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,433.80	795.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,626.76	159.04
Total Parts (\$\$)	7,807.04	636.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	350.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	180.00	0.00
4	TO APPLY UNDERCOATING	New	200.00	0.00
5	PANEL BEATING	New	1,400.00	380.00
6	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,200.00	600.00
Gross Labour Cost (\$)			3,410.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >