

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22001653/VTY3E2

**Date:** 29/04/2022

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00003972100		
<b>Claimant Vehicle No :</b>	SMS3121K	<b>Insured Vehicle No :</b>	SML4003Z		
Date of Loss:	17/02/2022	Nature of Claim:	TP	Claim No:	SNM22D201262/C02/TANCHC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS3121K	Engine No:	4J11CC3915
Make & Model:	MITSUBISHI OUTLANDER, 2.0 CVT SUNROOF (A)	Chassis No:	GF7W0700331
Reg. Date:	21/02/2020 (Man. Year: 2019)	Odometer:	17144 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,951.00	6,924.00	1,027.00	12.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,080.00	3,740.00	3,340.00	47.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>15,031.00</b>	<b>10,664.00</b>	<b>4,367.00</b>	<b>29.05</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	1,052.17	746.48	305.69	29.05
<b>Nett Amount (\$\$)</b>	<b>16,083.17</b>	<b>11,410.48</b>	<b>4,672.69</b>	<b>29.05</b>

### INSPECTION

Date of Assignment:	21/02/2022	
Date Inspected:	22/02/2022 Inspected At:	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ) 330 Ubi Road 3 Singapore 408650
Estimated Period of Repair:	5.0 days	

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 29 Apr 2022)

**Parts:** M1-SUV    MITSUBISHI OUTLANDER 2.0 CVT SUNROOF (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's    (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMS3121K)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE, FR BUMPER	Cut	863.00 FS	*863.00 FS
2	1		*BODY KIT	Scratched	1,554.00 FS	*1,554.00 FS
3	1		*GARNISH, FR BUMPER SI	Serviceable	48.00 FS	*- FS
4	6		*RIVET, FR BUMPER	Necessary	30.00 FS	*30.00 FS
5	4		*CLIP	Necessary	12.00 FS	*12.00 FS
6	10		*CLIP	Necessary	20.00 FS	*20.00 FS
7	20		*CLIP	Necessary	60.00 FS	*60.00 FS
8	1		*LH SIDE BRACKET, FR B	Serviceable	18.00 FS	*- FS
9	1		*RH SIDE BRACKET, FR B	Necessary	18.00 FS	*18.00 FS
10	1		*RH HEADLAMP ASSY	Cracked	1,948.00 FS	*1,948.00 FS
11	1		*RH FR FENDER	Dented	622.00 FS	*622.00 FS
12	1		*RH MOULDING, FR BUMPE	Scratched	97.00 FS	*97.00 FS
13	1		*RH FR WHEEL ARCH MOU	Scratched	168.00 FS	*168.00 FS
14	1		*RHF SPLASH SHIELD	Serviceable	164.00 FS	*- FS
15	1		*RH FR SUSP STRUT	Serviceable	410.00 FS	*- FS
16	1		*RH FR SUSP STRUT INS	Serviceable	137.00 FS	*- FS
17	1		*WHEEL, DISC	Scratched	974.00 FS	*974.00 FS
18	1		*YOKOHAMA V552 225/55	Serviceable	250.00 FS	*- FS
19	1		*RH DOOR MIRROR ASSY	Scratched	558.00 FS	*558.00 FS
					<b>Total Parts (S\$)</b>	<b>7,951.00      6,924.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DIAGNOSTIC / SCANNING	New	250.00	250.00
2	TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO REPLACE UNDERCARRIAGE DAMAGE PARTS	New	640.00	0.00
4	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT	New	280.00	280.00
5	WHEEL BALANCING	New	50.00	50.00
6	TO REPLACE FRONT BODY KIT	New	800.00	600.00
7	TO REPLACE FRONT BUMPER, RHF FENDER PNL, ETC - TO REPAIR RHF FENDER APRON. STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS	New	2,560.00	1,280.00
8	TO APPLY SEALANT KIT ON NEW PANEL	New	200.00	100.00
9	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS	New	2,200.00	1,100.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,080.00</b>	<b>3,740.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >