



**NATIONAL ASSESSMENT CENTRE SERVICES  
(LKK GROUP)**

**51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,  
Singapore 408933, TEL: 68410055 FAX: 68416315**

Your Ref : MT/1160745-003

Date: 28<sup>th</sup> Sep 2022

Our Ref : NS/INC22001656/Vqy3e2

**M/s Ntuc Income Insurance Co-operative Ltd**

73 Bras Basah Road  
#05-01 Ntuc Trade Union House  
Singapore 189556  
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SHB 6716Z  
INSURED VEHICLE: SCM 8369E  
ACCIDENT ON 07/02/2022**

Instruction was received to inspect the vehicle Reg. No. SHB 6716Z. The inspection was conducted on 07/02/2022 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 59 Loyang Drive, Singapore 508969.

The following vehicle information was recorded:

Registration Number	: SHB 6716Z
Make/Model	: Mercedes Benz Viano 2.2 CDI Trend Long
Year of Registration	: 2014
Body Colour	: White
Chassis Number	: WDF63981323858601
Engine Capacity	: 2143 cc
Speedometer Reading	: 761163 km

The vehicle sustained damages at the front and rear portion. The Estimated repair cost of such vehicle is S\$8,157.18 (Sin Dollars: Eight Thousand One Hundred Fifty-Seven and Eighteen Cents only.) (Exclude check items S\$3,541.68Nett) (Details see photographs enclosed)



**NATIONAL ASSESSMENT CENTRE SERVICES  
(LKK GROUP)**

**51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,  
Singapore 408933, TEL: 68410055 FAX: 68416315**

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Book Value	S\$ 34,468.47 (est)	
Less: LTA Reimbursement Value (RV)	(S\$ 32,869.00)	
Nett Liability	<u>S\$ 1,599.47</u>	
		S\$ 1,599.47

(b) If the vehicle to be "Repair"

Repair Cost (Est) (Exclude check items S\$3,541.68Nett)	<u>S\$ 8,157.18</u>	
Nett Liability		S\$ 8,157.18
(a) – (b) =		<u>(S\$ 6,557.71)</u> =====

The amount of estimated saving of S\$6,557.71 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:

Thevan Thomas Karthikesavan  
Automotive Assessor

K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.