



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7729K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER CENTRE MOULDING ASSY	SERVICEABLE	451.25	-
1	REAR BUMPER LOWER MOULDING ASSY	SERVICEABLE	155.00	-
10	REAR BUMPER COVER CLIPS @\$2.20	SERVICEABLE	22.00	-
1	REAR BUMPER FOGLAMP	SERVICEABLE	201.50	-
	LESS 20% DISCOUNT		-257.83	-
			1,031.32	-
NETT ITEMS				
1	REAR NO PLATE WITH TRIM COVER (N)	SERVICEABLE	55.00	-
1	REAR BUMPER REVERSE SENSOR (N)	SERVICEABLE	180.00	-
	LESS 10% DISCOUNT		-23.50	-
			211.50	-
SPECIAL NETT ITEMS				
1	REAR BUMPER MAT (SN)	SERVICEABLE	50.00	-
			50.00	-
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			820.00	630.00
GRAND TOTAL			2,112.82	630.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				630.00

Report Ref No. NS/INC22001657/Vvy3n2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.