

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3229Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FENDER LH	TO REPAIR SEE LABOUR	663.00	-
1	FENDER SHIELD LH	SERVICEABLE	174.90	-
2	FRONT BUMPER SIDE RH/LH	NECESSARY	14.30	14.30
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	2,256.40	-
1	FRONT DOOR WING LH	SCRATCHED	670.00	670.00
1	WHEEL HUB COVER	SCRATCHED	214.20	214.20
	LESS 20% DISCOUNT		-798.56	-179.70
			3,194.24	718.80
	<u>SPECIAL NETT ITEMS</u>			
1	FRT DOOR LOGO STICKER (SN)	NECESSARY	75.00	75.00
			75.00	75.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FENDER LH AND FRONT DOOR LH.		560.00	560.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK WIRING.		60.00	20.00
	TUFF KOTE.		60.00	20.00
			1,280.00	1,100.00
	GRAND TOTAL		4,549.24	1,893.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,500.00

Report Ref No. NS/INC22001658/Vvy3n2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.