

REPAIR ESTIMATE*

VEHICLE NO. SHD3229Y

DATE 29/01/2022

MAKE REG 12.05.2016

CHIANG / NTUC

MODEL HYU- I40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
				\$663.00
1	FENDER LH			\$174.90
1	FENDER SHIELD LH			\$14.30
1	FRONT BUMPER SIDE RH /LH			\$2,256.40
1	FRONT DOOR LH			\$670.00
1	FRONT DOOR WING LH			\$214.20
1	WHEEL HUB COVER			\$3,992.80
	SUB TOTAL			\$798.56
	20.00%			\$3,194.24
	DISCOUNTED TOTAL			\$75.00
1	FRT DOOR LOGO STICKER			\$75.00
	Labour Charge			\$560.00
	Panel Beating			\$600.00
	Spray Painting Charge			\$60.00
	Check wiring			\$60.00
	Tuff kote			\$1,220.00
	TOTAL LABOUR			\$4,489.24
	ESTIMATE TOTAL			4549.24
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

2

Thevan 82235769

7/2/22 1730

L/S after repair photo
2 days 3 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: