

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001666/BPA3Q2**Date:** 02/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210128772
Claimant Vehicle No :	SLV9996J	Insured Vehicle No :	SNC4782T
Date of Loss:	07/02/2022	Nature of Claim:	TP
		Claim No:	9626824133SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV9996J	Engine No:	2ZR8233359
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S (A)	Chassis No:	ZYX102084744
Reg. Date:	29/12/2017 (Man. Year: 2017)	Odometer:	74606 km
Colour:	Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,764.43	5,821.57	6,942.86	54.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	1,280.00	2,470.00	65.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,514.43	7,101.57	9,412.86	57.00
Approved Total (Overridden) (S\$)		5,650.00		
(S\$)	16,514.43	5,650.00	10,864.43	65.79
+ GST 7.00/7.00% (S\$)	1,156.01	395.50	760.51	65.79
Nett Amount (S\$)	17,670.44	6,045.50	11,624.94	65.79
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,752.95		
Global Sum Settlement (S\$)		6,750.00		

INSPECTION

Date of Assignment:	21/02/2022	Team Autopro Pte Ltd (sin Ming) (HQ)
Date Inspected:	21/02/2022 Inspected At:	160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
Estimated Period of Repair:	5.0 days	Singapore 575722

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Damaged	1,120.00 FL	*- FL
2	1		*BONNET INNER LOCK	Not Damaged	198.50 FL	*- FL
3	1		*FRONT BUMPER	Broken	869.90 FL	*869.90 FL
4	1		*FRONT BUMPER LOGO	Necessary	185.00 FL	*50.00 FL
5	2		*FRONT BUMPER SIDE RETAINER	Necessary	284.00 FL	*227.80 FL
6	1		*FRONT BUMPER INNER SPONGE	Not Damaged	358.20 FL	*- FL
7	1		*FRONT BUMPER CENTRE GRILLE	Broken	337.20 FL	*257.30 FL
8	1		*FRONT BUMPER LOWER GRILLE	Broken	686.20 FL	*370.90 FL
9	1		*FRONT BUMPER RADAR SENSOR	Scratched	2,781.60 FL	*1,850.50 FL
10	1		*FRONT SUPPORT PANEL	Not Damaged	978.00 FL	*- FL
11	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Damaged	166.30 FL	*- FL
12	1		*FRONT FENDER RH	Repair	1,233.00 FL	*- FL
13	1		*FRONT FENDER INNER COWLING RH	Not Damaged	377.75 FL	*- FL
14	1		*FRONT FENDER INNER COWLING BRACKET RH	Not Damaged	68.30 FL	*- FL
15	1		*FRONT FENDER ARCH GARNISH RH	No such part	371.82 FL	*- FL
16	1		*FRONT FENDER EMBLEM HYBRID	Necessary	108.00 FL	*85.70 FL
17	1		*HEADLAMP RH	Cut	2,898.00 FL	*1,770.00 FL
18	1		*HEADLAMP LOWER BRACKET RH	Not Damaged	182.30 FL	*- FL
19	1		*HEADLAMP PANEL RH	Not Damaged	388.50 FL	*- FL
20	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
21	1		*BONNET SEALANT	Not Necessary	100.00 FS	*- FS
22	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
23	1		*FRONT BUMPER CENTRE GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
24	1		*FRONT BUMPER LOWER GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
25	1		*FRONT BUMPER FOG LAMP W/GARNISH	Cut	480.00 FS	*420.00 FS
26	1		*FRONT BUMPER LOWER LIP (ARTISAN)	Broken	780.00 FS	*700.00 FS
27	1		*FRONT SUPPORT PANEL SEALANT	No such part	100.00 FS	*- FS
28	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	No such part	50.00 FS	*- FS
29	1		*FRONT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
30	1		*FRONT FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*FRONT FENDER ARCH GARNISH (ARTISAN)	Cut	450.00 FS	*380.00 FS
32	1		*FRONT FENDER ARCH GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*HEADLAMP OUTER GARNISH RH	Cut	180.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,162.57	7,192.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,398.14	1,370.53
Total Parts (\$\$)	12,764.43	5,821.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT BUMPER RADAR SENSOR	New	150.00	40.00
2	ALIGNMENT RADAR SENSOR	New	300.00	120.00
3	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
4	UPHOLSTERY	New	300.00	0.00
5	CHECK WIRING	New	100.00	0.00
6	PANEL BEATING	New	1,200.00	600.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,200.00	400.00
Gross Labour Cost (\$\$)			3,750.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >