

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001669/APA3Q2**Date:** 21/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100273150
Claimant Vehicle No :	SMP7534S	Insured Vehicle No :	SBN1368K
Date of Loss:	16/02/2022	Nature of Claim:	TP
		Claim No:	7124124286SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP7534S	Engine No:	L13B3937033
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GK33422543
Reg. Date:	14/10/2019 (Man. Year: 2019)	Odometer:	45954 km
Colour:	Black		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,216.00	4,046.88	6,169.12	60.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,610.00	2,450.00	3,160.00	56.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,826.00	6,496.88	9,329.12	58.95
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	15,826.00	5,200.00	10,626.00	67.14
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,656.45		

INSPECTION

Date of Assignment:	18/02/2022	
Date Inspected:	18/02/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	710.30 FL	*495.00 FL
2	1		*REAR BUMPER EXHAUST GARNISH	Not Necessary	29.10 FL	*- FL
3	2		*REAR BUMPER SIDE COVER GARNISH	Deformed	99.20 FL	*99.20 FL
4	1		*REAR BUMPER CENTER GARNISH	Deformed	192.10 FL	*192.10 FL
5	2		*REAR BUMPER SIDE RETAINER	Necessary	70.40 FL	*70.40 FL
6	1		*TAIL GATE	Dented	860.60 FL	*860.60 FL
7	1		*TAIL GATE LAMP	O/S Cut	386.40 FL	*193.20 FL
8	1		*TAIL GATE OUTER MOULDING	Not Necessary	197.80 FL	*- FL
9	1		*TAIL GATE LOGO	Not Necessary	37.10 FL	*- FL
10	1		*TAIL GATE EMBLEM FIT	Necessary	47.20 FL	*47.20 FL
11	2		*TAIL GATE DAMPER	Not Necessary	208.40 FL	*- FL
12	1		*TAIL GATE INNER HOLDER	Not Necessary	47.10 FL	*- FL
13	2		*TAIL GATE STOPPER	Not Necessary	24.00 FL	*- FL
14	1		*TAIL GATE INNER LOCK	Damaged	157.10 FL	*157.10 FL
15	1		*TAIL GATE LOCK CATCH	Not Necessary	25.00 FL	*- FL
16	1		*TAIL GATE WEATHERSTRIP	Cut	167.50 FL	*167.50 FL
17	1		*TAIL GATE INNER TRIM	Cracked	199.60 FL	*199.60 FL
18	2		*TAIL GATE HINGE	Not Necessary	131.60 FL	*- FL
19	1		*TAIL GATE DETECTOR	Cracked	267.30 FL	*145.00 FL
20	1		*TAIL GATE BUZZER	Damaged	126.10 FL	*126.10 FL
21	2		*TAIL GATE WINDSCREEN MOULDING	Necessary	190.00 FL	*190.00 FL
22	1		*TAIL LAMP	N/S Cut	594.80 FL	*297.40 FL
23	2		*REAR FENDER INNER COWLING	Not Necessary	194.20 FL	*- FL
24	1		*REAR FENDER INNER TRIM	N/S Torn	597.80 FL	*298.90 FL
25	1		*REAR END PANEL	Dented	394.10 FL	*394.10 FL
26	1		*REAR END PANEL TOP GARNISH	Deformed	164.30 FL	*164.30 FL
27	1		*REAR TOWING HOOK PANEL	Repair	297.30 FL	*- FL
28	1		*REAR FLOOR PANEL	Repair	796.10 FL	*- FL
29	1		*REAR FLOOR PANEL TOP BOARD	Deformed	198.60 FL	*198.60 FL
30	1		*REAR TOOLS COMPARTMENT SPONGE	Torn	212.30 FL	*212.30 FL
31	1		*REAR CHASSIS FRAME RH	Repair	849.20 FL	*- FL
32	1		*REAR CHASSIS TOP PANEL RH	Repair	295.50 FL	*- FL
33	1		*REAR EXHAUST PIPE	Repair	673.70 FL	*- FL
34	1		*REAR EXHAUST INSULATOR	Not Necessary	58.40 FL	*- FL
35	1		*SET REAR EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
36	4		*REAR EXHAUST MOUNTING	Not Necessary	84.80 FL	*- FL
37	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
38	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
39	1		*SET REAR BUMPER CENTER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
40	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	60.00 FS	*30.00 FS
41	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
42	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS
43	1		*TAIL GATE WINDSCREEN SOLAR FILM	Not Necessary	500.00 FS	*- FS
44	1		*SET TAIL LAMP CLIP	Necessary	50.00 FS	*20.00 FS
45	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
46	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	80.00 FS	*30.00 FS
47	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
48	1		*REAR TOWING HOOK PANEL SEALANT	Not Necessary	80.00 FS	*- FS
49	1		*REAR FLOOR PANEL SEALANT	Not Necessary	350.00 FS	*- FS
50	1		*REAR CHASSIS MEMBER TOP PANEL SEALANT RH	Not Necessary	120.00 FS	*- FS
51	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*SET REVERSE SENSOR (2 PCS)	Damaged	220.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					12,145.00	4,948.60
- List Item Discount on L Items 20.00/20.00% (\$)					1,929.00	901.72
Total Parts (\$)					10,216.00	4,046.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	1,800.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
9	REMOVE AND VIDEO FOOTAGE AND DISTANCE SETTING	New	80.00	50.00
10	REAR CHASSIS ALIGNMENT	New	250.00	0.00
11	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
12	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
13	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	150.00
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
Gross Labour Cost (\$\$)			5,610.00	2,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >