

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3444Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TORN	459.40	459.40
1	REAR BUMPER CENTRE MOULDING ASSY	DEFORMED	451.25	451.25
1	REAR BUMPER LOWER MOULDING ASSY	NOT NECESSARY	155.00	-
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER FOGLAMP	NOT NECESSARY	201.50	-
1	REAR BUMPER TOW COVER	DEFORMED	98.80	98.80
1	REAR BUMPER REINFORCEMENT	CRACKED	394.80	394.80
	LESS 20% DISCOUNT		-356.55	-285.25
			1,426.20	1,141.00
	NETT ITEMS			
1	REAR NO PLATE WITH TRIM COVER (N)	CRACKED	55.00	55.00
1	REAR BUMPER REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-23.50	-23.50
			211.50	211.50
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADV STICKER RH/LH @\$100.00 (SN)	NECESSARY	200.00	200.00
			250.00	250.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			820.00	630.00
	GRAND TOTAL		2,707.70	2,232.50





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,800.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22001678/Tty3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.