

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA22001679/KVY3E2**Date:** 11/11/2022**REFERENCE**

Insured/Claimant:	QUEK YUEN YONG JOHN	Policy No:	MP318783	
Date of Loss:	12/02/2022	Nature of Claim:	OD	Claim No: MPC03181

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU8218H	Engine No:	FB20YE32349
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Chassis No:	JF1SJ5KC5JG111705
Reg. Date:	16/08/2018 (Man. Year: 2018)	Odometer:	47455 km
Colour:	Metallic Dark Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	S\$81,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 9 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,289.35	3,753.75	1,535.60	29.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,620.00	2,000.00	620.00	23.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,909.35	5,753.75	2,155.60	27.25
- Excess (S\$)	0.00	3,375.00	-3,375.00	
(S\$)	7,909.35	2,378.75	5,530.60	69.92
+ GST 7.00/7.00% (S\$)	553.65	166.51	387.14	69.93
Nett Amount (S\$)	8,463.00	2,545.26	5,917.74	69.92

INSPECTION

Date of Assignment:	21/02/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected:	22/02/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell)
			205 Braddell Road
			Singapore 579701
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2022)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU8218H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT LH DOOR (WCP)	Bent	550.00 F	*550.00 F
2	1	*FRONT LH DOOR OUTER HANDLE (WCP)	Cut	30.00 F	*30.00 F
3	1	*FRONT LH DOOR HINGE TOP (WCP)	Repair	35.00 F	*- F
4	1	*FRONT LH DOOR HINGE LOWER (WCP)	Repair	35.00 F	*- F
5	1	*FRONT LH DOOR FRAME BLACK STICKER(REAR) (WCP)	Necessary	18.00 F	*18.00 F
6	1	*FRONT LH DOOR FRAME BLACK STICKER(TOP) (WCP)	Necessary	18.00 F	*18.00 F
7	1	*FRONT LH DOOR FRAME BLACK STICKER(FRONT) (WCP)	Necessary	5.00 F	*5.00 F
8	1	*FRONT LH DOOR GLASS OUTER MOULDING (WCP)	Serviceable	70.00 F	*- F
9	1	*FRONT LH DOOR WEATHER STRIP (WCP)	Serviceable	90.00 F	*- F
10	1	*LH WING MIRROR WITH BODY (WCP)	Cracked	475.00 F	*330.00 F
11	1	*LH WING MIRROR SIGNAL LAMP (WCP)	Cut	75.00 F	*75.00 F
12	1	*LH FRONT FENDER (WCP)	Bent	270.00 F	*270.00 F
13	1	*LH FRONT FENDER CORNER COVER (WCP)	Serviceable	10.00 F	*- F
14	1	*LH FRONT FENDER INNER SHIELD (WCP)	Serviceable	75.00 F	*- F
15	8	*LH FRONT FENDER INNER SHIELD CLIP (WCP)	Not Necessary	16.00 F	*- F
16	1	*FRONT BUMPER LH SIDE RETAINER (WCP)	Distorted	10.00 F	*10.00 F
17	1	*FRONT BUMPER (WCP)	Repair	620.00 F	*- F
18	1	*LH ENGINE TOP SIDE TRIM (WCP)	Cracked	20.00 F	*20.00 F
19	5	*LH ENGINE TOP SIDE TRIM CLIP (WCP)	Necessary	12.50 F	*12.50 F
20	1	*BONNET (WCP)	Bent	650.00 F	*650.00 F
21	12	*BONNET INSULATOR CLIP (WCP)	Necessary	24.00 F	*24.00 F
Supplementary #1					
22	1	*LH HEADLAMP (WCP)	Broken	1,400.00 F	*1,400.00 F
Supplementary #2					
23	1	*REAR BOOT LOCK MODULE (WCP)	Not Consistent with the impact	300.00 F	*- F

F=Franchise part.

Sub Total (\$\$) 4,808.50 3,412.50

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				+ Margin on L,N Items 10.00/10.00% (S\$)	480.85	341.25
				Total Parts (S\$)	5,289.35	3,753.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO JACK,STRAIGHTEN ON LH FRONTFENDER INNER PANEL,A PILLAR ,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	1,000.00	800.00
2	TO PUTTY,RESPRAY ON FRONT BUMPER,LH FRT FENDER,INNER PANEL,A PILLAR ,LH FRT DOOR ,LH REAR DOOR AND AFFECTED AREAS	New	1,300.00	1,100.00
3	CHECK LIGHTING AND WIRING	New	30.00	20.00
4	TO REMOVE,TRANSFER PARTS TO NEW DOOR	New	150.00	80.00
5	CHECK AND ADJUST WHEEL ALIGNMENT	New	60.00	0.00
6	REPLACE AND RESPRAY WING MIRROR LH	New	80.00	0.00
Gross Labour Cost (\$\$)			2,620.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >