SS. REC. BY: Taylor REF: INC. ASSIG	GNMENT	
	SUMAIRUT	Yr Regn: 20/6 / Dec
on Date:	Veh No: Type: M.Car / M.Cycle / Bus / Van / Lorr	
stimated Cost:	Truck / Trailer or	0
D KTP / WS / TP RES / OD RES / EVA / INV / MV	U. sundar'	40. c.c /685
o Inspect Vehicle No:	Wake.	A/C: Insured / Std / NI / NA
i Workshop m/s	Colour Yells as	T/Radio; Insured / Std / NI / NA
f	Sp.Reading +55727	1/Radio; insured / Std / Ni / NA
nsuited:	Eng/No:	221
Policy No.		414 MH409777
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt	`
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked /	-
(Client's Record)	Brake: Inorder / Jammed / Leaked /	
Make of Veh:	Modi: Nit / S/Rim / STD A/Rim or	
	Tyre Size: F: 205/	60KC6
(Policy Condition)	R:	4
Remark: The veh had commenced its N/S 0/S	BS / DUN / EXNOVA / GY / FS / LIZA /	MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or	mole
Bal. or Market Value:	Front	Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm	R/Balmm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm	L/Bal. 6 mm
Est Repairs: days Res.: Yes or No	D.O.A.	D.O.I. 21/2/22
Lum Sum: % 3 Val.: Yes or No	Survey held at	+ Cozy
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S	I NIS I WID I Rooftop or
Vehicle: IN / OU	T	h. Characture officeted due to collision
Date.	_ The U/C / Chassis frame / Boo	ly Structure affected due to collision
Date / Time Action / Instruction	*	
1		3
Date/Time, File Pass to? : Preli. Report	Days Of Repair:	
; Final Report	Resurvey No. of Trip:	Survey Fee:
Date/Time, File Return to?		Transportation:
2) Add F	ee: : Site Insp (\$	)\$ ÷ RSSI
	: Interview (\$	) Photos
Reput Formal :	:Tech. Invs (\$	) Others
	: Weel:end (%	1
Lump Sum / LBJ: (\$)	. 2007-1101	
Lump Sum / LBJ: (†)		TOTAL

## Sheet2

## **COMFORT TRANSPORTATION PTE LTD** REPAIR ESTIMATE

Vehicle No. : SHA9184T

Make : HYUNDAI

Model :1-40

Date: 21/02/2022

Insurance: NTUC

MVA: MS. LOKE YY

/lodel	: 1-40		MVA: MS. LOKE YY		
Qty	Parts Description / Labour	Туре	Unit Price	Amount	
	1 REAR BUMPER COVER			\$1,106.00	
	1 REAR BUMPER CLIPS			\$22.00	
	1 REAR BUMPER REINFORCEMENT			\$428.40	
	2 RR BUMPER REINFORCEMENT BRACKET RH LH		\$160.60	\$321.20	
	1 REAR BUMPER SPONGE			\$119.50	
	1 REAR BUMPER UNDER COVER			\$228.00 044	
	1 REAR BUMPER REFLECTOR LAMP LH			\$32.00	
	2 TAIL LAMP LH			\$697.80	
	1 BOOTLID			\$2,609.48	
	2 BOOTLID HINGE LH RH		\$142.30	\$284.60	
	1 BOOTLID 'H' EMBLEM			\$63.10	
	1 BOOTLID CRDI PLATE			\$52.40	
	1 BOOTLID MOULDING			\$85.00	
	1 BOOTLID 140 EMBLEM			\$67.90	
	1 BOOTLID ABSORBER			\$65.65	
	1 BOOTLID LOWER GARNISH			\$227.90	
	1 BOOTLID LOCK UPPER			\$114.90	
	1 BOOTLID KEY LOCK			\$68.00 X	
	1 BOOTLID LAMP LH / RH		\$622.20	\$1,244.40 HY? Rh	
	1 LICENSE LAMP			\$56.10	
	1 REAR PANEL			\$526.70 RY	
	1 REAR PANEL GARNISH			\$57.70 de	
	1 REAR PANEL LOWER PANEL			\$495.50	
	1 TAIL LAMP LOWER PANEL LH			\$225.60	
	1 EXHAUST SILENCER LH			\$967.70 🔀	
	1 EXHAUST PIPE CENTRE			\$730.10	
	1 EXHAUST PIPE HANGER			\$117.10	
	SUB TOTAL			\$11,014.73	
	LESS 20%			\$2,202.95	
	DISCOUNTED TOTAL			\$8,811.78	
	REAR BUMPER ADVERTISEMENT LOGO		1	\$50.00 Nett	
	Page 1				

Sheet2

REAR FENDER ADVERTISEMENT LOGO LH REAR FENDER ADVERTISEMENT LOGO RH BOOTLID ADVERTISEMENT LOGO BOOTLID CITYCAB LOGO & TEL NO STICKER REAR BUMPER REVERSE SENSOR REAR NUMBER PLATE	-10% -10% -10%	\$100.00 \$100.00 \$60.00	Nett W - Nett NW - Nett X
Labour Charge PANEL BEATING SPRAY PAINTING CHARGE CHECK ALL LIGHTING TUFF KOTE REMOVE/REFIX REVERSE SENSOR TOTAL LABOUR ESTIMATE TOTAL		\$1,200.00 \$750.00 \$60.00 \$60.00 \$60.00 \$2,130.00	30
			1

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tauffer 97495747

WP 71/7/22 E 415pm

4/5 Alsung Afringer

3 deys

Janfthi CHillandren

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755 Workshops 205 Briddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 Date/Time: 21.02.2022 10:26 Page: 1

Team: ARC Repair TP(CFSO)1	JOB CARD Sal	es Order: 417625	3 JC NO305505872
USTOMER		REGN NO.: SHA9184T	MILEAGE
R/MS CITYCAB PTE LTD  USTOMER NO. 7010070  DDBESS 383 SIN MING DRIVE	-	MAKE: HYUNDAI	FUEL E1/2F
Singapore SINGAPORE 575717	,	MODEL I-40	20.02.2022 11:15
EL. (R) 65551188 (O)	-	YR OF MANU. 22.12.2016 CHASSIS CODE	TARGET DATE  COMPLETION DATE/TIME:
ISCOUNT CARD NO.		KMHLB41UMHUO	
Accident Date: 20.02.2022 NATURE: 3P 20.02.2022	JOB DESCRIPTION		
S/NO LABOR CODE	DESCRIP	TION	REAR PROPERTY OF THE PROPERTY
HECKED & PASSED OUT BY:			
SERVICE ADVISOR		CUS	TOMER'S SIGNATURE
owledgement Slip	Exit Pass		
e: lo.: :le No.: SHA9184T YY	Vehicle No.:	9184T	
e of Service Advisor Signature/Date	Name of Service Advi	sor Da	ate
returned to Service Reception upon collection	To be kept by Security	y Guard	