

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI22001684/TTY3N2**Date:** 23/03/2022**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR005847
Claimant Vehicle No :	SHD4502B	Insured Vehicle No :	SMW1261G
Date of Loss:	21/02/2022	Nature of Claim:	TP
		Claim No:	M2200924

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4502B	Engine No:	G4LEKU298709
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU164904
Reg. Date:	24/07/2019 (Man. Year: 2019)	Odometer:	297866 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,175.68	138.88	2,036.80	93.62
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,410.00	850.00	560.00	39.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,596.68	999.88	2,596.80	72.20
+ GST 7.00/7.00% (S\$)	251.77	69.99	181.78	72.20
Nett Amount (S\$)	3,848.45	1,069.87	2,778.58	72.20

INSPECTION

Date of Assignment:	22/02/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	21/02/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Mar 2022)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD4502B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER COVER	Repair	430.90 FL	-	*- FL
2	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*FRT BUMPER BRACKET LH	Not Necessary	28.00 FL	-	*- FL
4	1		*HEADLAMP LH	Not Necessary	1,993.65 FL	-	*- FL
5	1		*FRT BUMPER SIDE GRILLE LH	Not Necessary	93.45 FL	-	*- FL
6	1		*EMBLEM – BLUE DRIVE LH	Necessary	26.60 FL	-	*26.60 FL
7	1		*FRT FENDER ADVERTISEMENT LOGO LH	Cut	100.00 F	-	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,694.60	148.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	518.92	9.72
Total Parts (\$\$)	2,175.68	138.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	750.00	350.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	CHECK ALL LIGHTING	New	60.00	0.00
Gross Labour Cost (\$\$)			1,410.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >