

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001685/BQY3M4**Date:** 20/07/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00113152100
Claimant Vehicle No :	GBJ1717H	Insured Vehicle No :	YJ1319B
Date of Loss:	15/02/2022	Nature of Claim:	TP
		Claim No:	SNM22D201144/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ1717H	Engine No:	1KD2849207
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y10K212834
Reg. Date:	30/04/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R12C
Front Left Side:	GREEN-MAX 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	GREEN-MAX 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,286.05	3,755.60	2,530.45	40.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,260.00	2,170.00	63.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,716.05	5,015.60	4,700.45	48.38
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	9,716.05	4,000.00	5,716.05	58.83
+ GST 7.00/7.00% (\$\$)	680.12	280.00	400.12	58.83
Nett Amount (\$\$)	10,396.17	4,280.00	6,116.17	58.83

INSPECTION

Date of Assignment:	30/05/2022	
Date Inspected:	02/03/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	9.0 days	

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Jul 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ1717H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,116.70 FL	*1,000.00 FL
2	1		*TAILGATE RH SIDE HINGE	Not Damaged	55.10 FL	*- FL
3	1		*TAILGATE RH CENTRE HINGE	Not Damaged	55.10 FL	*- FL
4	1		*TAILGATE LH CENTRE HINGE	Bent	55.10 FL	*55.10 FL
5	1		*TAILGATE LH SIDE HINGE	Bent	55.10 FL	*55.10 FL
6	1		*TAILGATE LOWER PANEL	Not Damaged	278.40 FL	*- FL
7	1		*TAILGATE LOWER PANEL LH SIDE BRACKET	Bent	78.30 FL	*78.30 FL
8	1		*TAILGATE LOWER PANEL LH SIDE BRACKET RUBBER	Missing	26.30 FL	*26.30 FL
9	1		*TAILGATE LOWER PANEL RH SIDE BRACKET	Not Damaged	78.30 FL	*- FL
10	1		*TAILGATE LOWER PANEL RH SIDE BRACKET RUBBER	Not Damaged	26.30 FL	*- FL
11	1		*TAILGATE RH HINGE LOCK	Jammed	124.00 FL	*106.00 FL
12	1		*TAILGATE LH HINGE LOCK	Jammed	124.00 FL	*106.00 FL
13	1		*RH TAILLAMP ASSY	Not Damaged	288.70 FL	*- FL
14	1		*RH TAILLAMP BRACKET	Not Damaged	31.80 FL	*- FL
15	1		*LH TAILLAMP ASSY	Not Damaged	288.70 FL	*- FL
16	1		*LH TAILLAMP BRACKET	Not Damaged	31.80 FL	*- FL
17	1		*REAR NUMBER PLATE LAMP	Not Damaged	33.50 FL	*- FL
18	1		*REAR NUMBER PLATE BRACKET	Not Damaged	101.20 FL	*- FL
19	1		*EXHAUST PIPE	Not Damaged	634.00 FL	*- FL
20	1		*EXHAUST PIPE GASKET	Not Damaged	55.00 FL	*- FL
21	1		*REAR NUMBER PLATE	Not Damaged	60.00 FS	*- FS
22	1		*TAILGATE LOWER PANEL JOINT SEALANT	Not Necessary	70.00 FS	*- FS
23	1		*TAILGATE ADVERTISEMENT STICKER	Necessary	750.00 FS	*350.00 FS
24	1		*TAILGATE 70KM/H STICKER	Necessary	24.00 FS	*24.00 FS
25	1		*TAILGATE 7PAX STICKER	Necessary	24.00 FS	*24.00 FS
26	1		*SET REAR REVERSE SENSOR	Short Circuit	340.00 FS	*200.00 FS
27	1		*REAR STEP BRACKET	Bent	220.00 FS	*100.00 FS
28	1		*RH SIDE GATE	Dented	1,430.00 FL	*1,325.00 FL
29	1		*LH SIDE GATE	Dented	1,430.00 FL	*1,325.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,885.40	4,774.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,599.35	1,019.20
Total Parts (\$\$)	6,286.05	3,755.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,000.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	50.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	0.00
5	REMOVE AND REPLACE REAR REVERSE SENSORS TO ASSIST REPAIR	New	100.00	60.00
6	LABOUR	New	600.00	0.00
7	PAINTING	New	600.00	0.00
Gross Labour Cost (\$\$)			3,430.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >