LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22001689/KTF3E2

Date: 16/06/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001960344

Claimant Vehicle SLL7613E Insured Vehicle No : SLK9042U

Date of Loss: 21/02/2022 Nature of Claim: TP Claim No: 270155

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL7613E

Make & Model:TOYOTA HARRIER, 2.0 ELEGANCE CVT (A)Engine No:3ZRB910860Reg. Date:09/03/2017 (Man. Year: 2016)Chassis No:ZSU600092084Colour:Metallic MaroonOdometer:418303 km

Engine Capacity: 1986 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17 Rear Tyre Size: 225/65 R17
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,398.67	4,398.67	0.00	0.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,110.00	980.00	130.00	11.71
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,508.67	5,378.67	130.00	2.36
	Approved Total (Overridden) (S\$)		4,300.00		
	(S\$)	5,508.67	4,300.00	1,208.67	21.94
	+ GST 7.00/7.00% (S\$)	385.61	301.00	84.61	21.94
	Nett Amount (S\$)	5,894.28	4,601.00	1,293.28	21.94

INSPECTION

Date of Assignment: 22/02/2022

Cheng Hoe Motor Pte Ltd (AMK)

Date Inspected: 11/04/2022 Inspected At: 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT

Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 May 2022)

Parts: M1-SUV TOYOTA HARRIER 2.0 ELEGANCE CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLL7613E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	495.60 FL	*495.60 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	115.20 FL	*115.20 FL
3	6		*FRONT BUMPER CLIP	Necessary	27.00 FL	*27.00 FL
4	1		*HEADLAMP LH	Mtg Cracked / Cut	3,511.90 FL	*3,511.90 FL
5	1		*FRONT LH FENDER	Bent	1,446.30 FL	*1,446.30 FL
6	1		*FRONT LH FENDER INNER SHIELD	Deformed / Distorted	246.70 FL	*246.70 FL
7 E-Err	6	part. L=ListIte	*FRONT LH FENDER INNER SHIELD CLIP	Necessary	22.20 FL	*22.20 FL
1 -1 16	111011136	part. L-Listite	SHIDISC.	Sub Total (S\$)	5,864.90	5,864.90
			- List Item Discount or	L Items 25.00/25.00% (S\$)	1,466.23	1,466.23
				Total Parts (S\$)	4,398.67	4,398.67
			Report was unsubmitted dur	ing this print-out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE AND REFIX FRT BUMPER & ATTACHMENTS, GRILLE, LH HEADLAMPS, FRT LH FENDER, KNOCK AND REPAIR FRT LH FENDER INNER PANEL AND RE-ALIGN TO SAME	New	500.00	400.00
2	TO PUTTY AND RESPRAY ON FRT BUMPER & ATTACHMENTS, FRT LH FENDER & INNER PANEL AND ALL AFFECTED AREAS	New	580.00	550.00
3	RUSTPROOFING	New	30.00	30.00
	Gross Labou	r Cost (S\$)	1,110.00	980.00
	Report was unsubmitted during this	print-out		

< END OF ESTIMATES >