

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	HSBC LIFE (SING	APORE) PTE LTD	Re	ef:	CC4/ASM22001695/Upa3q2	
	10 MARINA BOULI #48-01 MARINA BA 2SINGAPORE 018	AY FINANCIAL CENTRE TOWER	Da	ate:	19/04/2023	
	ATTN:WINNIE		Co	ode:	HSB	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJV 2438Z	Veh. Inspected		SKR 2752A	
	Policy No.	P2455950	Coverage (\$)		0.00	
	Claim No.	S2M03TWN	Excess (\$)		0.00	
	Assign From		Assign Date		22/02/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HARRIER 2.0 PREMIUM (A)	c.c		1986	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	ZSU600030353	Colour		WHITE	
	Odometer	181056 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	235/55 R18	BRIDGESTONE		7 mm	
	L/H Front Tyre	235/55 R18	BRIDGESTONE		7 mm	
	R/H Rear Tyre	235/55 R18	BRIDGESTONE		7 mm	
	L/H Rear Tyre	235/55 R18	BRIDGESTONE		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	21/02/2022	Inspection Date		22/02/2022	
	Survey held at	FASTECH AUTO PTE LTD				
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	STIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				