



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:GARNET			Ref: CC4/ASM22001697/Apa3q2 Date: 02/08/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKL 8308S	Veh. Inspected	SKL 5645M
	Policy No.	GA250428	Coverage (\$)	0.00
	Claim No.	S2M03S94	Excess (\$)	0.00
	Assign From		Assign Date	21/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	MINI COOPER	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WMWSV32080T672411	Colour	GREY
	Odometer	91824 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45 R17	MICHELIN	6 mm
	L/H Front Tyre	215/45 R17	MICHELIN	6 mm
	R/H Rear Tyre	215/45 R17	MICHELIN	6 mm
	L/H Rear Tyre	215/45 R17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/01/2022	Inspection Date	21/02/2022
	Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	