

TPAYA  
X140Tory.

SKL5645M 2013 Nov

Mini Cooper 1598cc

WMW SV3208OT672411

|                                          |              |                      |   |
|------------------------------------------|--------------|----------------------|---|
| Rear Bumper                              | torn         | 962                  | ✓ |
| Rear Bumper Clips                        | New          | 30(SN)               | ✓ |
| Rear Bumper Side Holder x 2              | x 2 m        | $55 \times 2 = 110$  | X |
| Rear Bumper Lower Greenish               | delid        | 345                  | ✓ |
| Rear Bumper Grille                       | and          | 258                  | ✓ |
| Rear Bumper Reflector RH                 | and          | 185                  | ✓ |
| Rear Bumper Reflector Chrome Greenish RH | New          | 76                   | X |
| Rear Bumper Reinforcement                | HP m         | 435                  | X |
| Reverse Sensor x 02                      | 1 piece dnyd | 240                  |   |
| Reverse Sensor Holder x 04               |              | $240 \times 2 = 480$ | X |
|                                          |              | $22 \times 4 = 88$   | X |

1090

1791

S.N. 30.

SKL564SM.

Panel Beating

Spray Painting.

Wiring.

To remove cruise sensor -

To perform diagnostic test

700

~~400~~ 250

~~500~~ 250

~~50~~ 30

~~100~~ 50

~~200~~ 120

total: 2521.50

L/S: 2K

03 Days

2K  
3 days

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: