

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 7153B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	DENTED / DEFORMED	911.20	819.40
1	FRONT BUMPER FOG LAMP O/S (CONSISTENT)	CRACKED	450.00	282.30
1	FRONT BUMPER FOG LAMP GARNISH O/S (CONSISTENT)	GRAZED	182.30	105.20
1	FRONT BUMPER SENSOR (CONSISTENT)	NOT NECESSARY	220.00	-
1	FRONT BUMPER SIDE RETAINER O/S (CONSISTENT)	NECESSARY	65.50	45.50
1	FRONT BUMPER BEAM (CONSISTENT)	DENTED	288.40	288.40
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT GRILLE ASSY (CONSISTENT)	SCRATCHED / CRACKED	1,220.30	680.30
1	FRONT FENDER O/S (CONSISTENT)	TO REPAIR SEE LABOUR	845.20	-
1	HEADLAMP O/S (CONSISTENT)	HOLDER CRACKED	2,655.30	2,433.60
1	HEADLAMP BRACKET O/S (CONSISTENT)	CRACKED	68.50	68.50
1	FRONT LICENCE PLATE (CONSISTENT)	SCRATCHED	50.00	50.00
1	FRONT SUPPORT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	655.20	-
	LESS 20% DISCOUNT		-	-962.64
			7,651.90	3,850.56
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX FRONT BUMPER SENSOR.		80.00	40.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER O/S AND FRONT SUPPORT PANEL.		680.00	350.00
	TO PUTTY & SPRAY PAINTING.		900.00	500.00
			1,880.00	910.00
	GRAND TOTAL		9,531.90	4,760.56

Report Ref No. CS/ASM22001700/Uty3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	3,800.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CS/ASM22001700/Uty3e2

CHUA KANG SENG
Licensed Appraiser