

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001704/BTY3N2**Date:** 23/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00103102100		
Claimant Vehicle No :	SLN8154X	Insured Vehicle No :	GBC2242R		
Date of Loss:	18/02/2022	Nature of Claim:	TP	Claim No:	SNM22D201248/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8154X		
Make & Model:	HONDA SHUTTLE, 1.5 G (A)	Engine No:	L15B3536916
Reg. Date:	18/05/2017 (Man. Year: 2016)	Chassis No:	GK81005892
Colour:	Grey	Odometer:	144272 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50R16	Rear Tyre Size:	205/50R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,061.26	6,190.80	4,870.46	44.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,110.00	2,060.00	2,050.00	49.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,171.26	8,250.80	6,920.46	45.62
Approved Total (Overridden) (\$\$)		6,600.00		
(\$\$)	15,171.26	6,600.00	8,571.26	56.50
+ GST 7.00/7.00% (\$\$)	1,061.99	462.00	599.99	56.50
Nett Amount (\$\$)	16,233.25	7,062.00	9,171.25	56.50

INSPECTION

Date of Assignment:	22/02/2022	
Date Inspected:	22/02/2022 Inspected At:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	8.0 days	

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Mar 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 G (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN8154X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	989.30 FL	*867.00 FL
2	1		*REAR BOOT LOCK	Jammed	164.20 FL	*164.20 FL
3	2		*REAR BOOT HINGE L+R	Not Damaged	182.40 FL	*- FL
4	1		*REAR BOOT W/STRIP	Torn	137.50 FL	*137.50 FL
5	1		*REAR BOOT LOGO	Necessary	84.60 FL	*29.60 FL
6	2		*REAR BOOT LAMP L+R	Broken	968.60 FL	*968.60 FL
7	1		*REAR BOOT INSULATOR	Not Necessary	167.50 FL	*- FL
8	10		*REAR BOOT INSULATOR CLIP	Not Necessary	50.00 FL	*- FL
9	1		*REAR BOOT EMBLEM SHUTTLE	Necessary	79.30 FL	*48.60 FL
10	1		*REAR BOOT SPOILER	Not Necessary	674.20 FL	*- FL
11	1		*REAR BOOT INNER TRIM	Broken	458.60 FL	*243.80 FL
12	1		*REAR BOOT INNER TRIM HANDLE	No such part	83.70 FL	*- FL
13	1		*REAR BOOT GARNISH	Broken	465.30 FL	*383.10 FL
14	1		*REAR BOOT CHROME	Broken	176.40 FL	*176.40 FL
15	1		*REAR BOOT W/S GLASS	Broken	885.60 FL	*885.60 FL
16	1		*REAR BOOT W/S GLASS MOULDING	Necessary	164.70 FL	*138.90 FL
17	2		*REAR BOOT NUMBER PLATE LAMP L+R	Not Damaged	86.40 FL	*- FL
18	1		*REAR BOOT NUMBER PLATE LAMP GARNISH	Not Damaged	143.20 FL	*- FL
19	2		*REAR BUMPER RETAINER RL	Necessary	238.00 FL	*44.40 FL
20	1		*REAR BUMPER	Broken	883.50 FL	*883.50 FL
21	2		*REAR BUMPER BEAM	No such part	148.00 FL	*- FL
22	2		*REAR BUMPER BRACKET L+R	No such part	96.00 FL	*- FL
23	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
24	2		*REAR BUMPER MUDFLAP RH	Not Damaged	185.70 FL	*- FL
25	1		*REAR BUMPER UNDER COVER	Not Damaged	152.70 FL	*- FL
26	1		*TAIL LAMP L+R (2 Pcs)	Broken (1 Pc only)	664.80 FL	*332.40 FL
27	2		*TAIL LAMP PANEL L+R	Not Damaged	328.40 FL	*- FL
28	1		*TAIL LAMP CLIP L+R (2 Pcs)	Necessary (1 Pc only)	10.00 FL	*5.00 FL
29	1		*REAR END PANEL	Dented	623.70 FL	*450.00 FL
30	1		*REAR END PANEL TOP GARNISH	Broken	128.80 FL	*117.90 FL
31	1		*SPARE WHEEL PANEL	Dented	987.30 FL	*632.00 FL
32	1		*SPARE WHEEL PANEL TOP BOARD	Not Damaged	377.20 FL	*- FL
33	2		*SPARE WHEEL PANEL SIDE PANEL L+R	Not Damaged	484.60 FL	*- FL
34	1		*REAR W/S GLASS SEALANT	Necessary	100.00 FS	*30.00 FS
35	1		*REVERSE CAMERA	Short Circuit	532.80 FS	*250.00 FS
36	2		*REVERSE SENSOR	Short Circuit	560.00 FS	*200.00 FS
37	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
38	1		*BOOT W/STRIP MOTOR	Short Circuit	452.30 FS	*390.00 FS
39	1		*SPARE WHEEL PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
40	1		*SPARE WHEEL PANEL INSULATOR	No such part	150.00 FS	*- FS
41	1		*REAR NUMBER PLATE	Broken	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,325.30 7,498.50
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,264.04 1,307.70

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					11,061.26	6,190.80
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT DAMAGE PARTS,TO CUT/WELD,KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	1,800.00	1,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,600.00	800.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	120.00	0.00
4	TO R&R REAR BOOT MECHANISM	New	80.00	80.00
5	TO R&R REAR LUGGAGE COMPARTMENT	New	80.00	0.00
6	TO R&R UPHOSTERY,GARNISH AND ATTACHMENT PARTS	New	150.00	0.00
7	TO R&R REVERSE SENSOR AND CHECK FUNCTION	New	60.00	60.00
8	TO CHECK WHEEL ALIGNMENT	New	80.00	0.00
9	TO R&R REAR W/S GLASS	New	140.00	120.00
Gross Labour Cost (\$\$)			4,110.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >