

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001705/VTY3N2**Date:** 25/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00003272100

Claimant Vehicle No : GBK2612P **Insured Vehicle No :** GBD6830L

Date of Loss: 14/02/2022 Nature of Claim: TP Claim No: SNM22D201152/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK2612P**

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2866989

Reg. Date: 12/03/2020 (Man. Year: 2019) Chassis No: JTFAT35Y60K214384

Colour: White Odometer: 48614 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75R15 Rear Tyre Size: 195/75R15

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,366.20	1,075.76	3,290.44	75.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	830.00	1,720.00	67.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,916.20	1,905.76	5,010.44	72.44
+ GST 7.00/7.00% (\$\$)	484.13	133.40	350.73	72.45
Nett Amount (\$\$)	7,400.33	2,039.16	5,361.17	72.45

INSPECTION

Date of Assignment: 22/02/2022

Date Inspected: 23/02/2022 Inspected At: Dickson Auto Care Centre Pte Ltd (HQ)
29 Ubi Road 4, Dickson Auto Centre
Singapore 408619

Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Mar 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK2612P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Serviceable	411.90 F	*- FL
2	1		*FRONT HEADLAMP LH & RH (2 Pcs)	Scratched	1,631.00 F	*815.50 FL
3	1		*FRONT GRILLE	Scratched	572.60 F	*438.85 FL
4	1		*FRONT GRILLE LOGO	Scratched	75.00 F	*75.00 FL
5	1		*FRONT GRILLE DYNA LOGO	Necessary	65.00 F	*65.00 FL
6	1		*FRONT NO PLATE	Serviceable	24.00 FS	*- FS
7	10		*FRONT GRILLE CLIPS	Necessary	100.00 FS	*30.00 FS
8	1		*FRONT PANEL (ABOVE FRONT GRILLE)	Repair	1,195.00 FS	*- FS
9	1		*FRONT UPPER PANEL (WIPER PANEL)	Repair	291.70 FS	*- FS
					Sub Total (S\$)	4,366.20 1,424.35
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00 348.59
					Total Parts (S\$)	4,366.20 1,075.76

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX FRONT WIRING,HEADLAMP & TEST FOR PROPER FUNCTIONING	New	100.00	30.00
2	TO REMOVE & REFIX AIRCON PARTS TO ASSISTS TO REPAIR & REFILL AIRCON GAS R134 & SOMPRESSOR OIL	New	450.00	0.00
3	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS.PANEL BEAT,CUT AND WELD NEW PARTS & PANELS WITH FULL REALIGNMENT	New	1,000.00	400.00
4	TO PROVIDE SKILL LABOUR AND MATERIAL TO PREPARE AND PAINT ALL NEW PARTS AND PANELS	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,550.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >