

Your Ref : SNM22D201078/C01/TANKL

Date: 17<sup>th</sup> May 2022

Our Ref : CS/CTI22001706/Kqy3e2

**M/s China Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMQ 626B  
ACCIDENT ON 10/02/2022**

Instruction was received to inspect the vehicle Reg. No. SMQ 626B. The inspection was conducted on 22/02/2022 at the premises of M/s Ding Auto Pte Ltd, Blk 10 #01-20 Sin Ming Ind Est Sec C, Singapore 575645.

The following vehicle information was recorded:

Registration Number	: SMQ 626B
Make/Model	: Mercedes Benz E220D SE Auto
Year of Registration	: 2019
Body Colour	: Metallic Black
Chassis Number	: WDD2130042A62080B
Engine Capacity	: 1950 cc
Speedometer Reading	: Nil

The vehicle caught fire. The cause of fire probably due to short circuit at the engine compartment. The Estimated repair cost of such vehicle is S\$58,969.34 (Sin Dollars: Fifty-Eight Thousand Nine Hundred Sixty-Nine and Thirty-Four cents only.) (Exclude check items S\$24,090.00Nett) (Details see photographs enclosed)

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 170,000.00 (est)

Less: LTA Reimbursement Value (RV)

(S\$ 83,055.00)

Less: Excess

S\$ 86,945.00  
(S\$ 1,250.00)

Nett Liability

S\$ 85,695.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 58,969.34

(Exclude check items S\$24,090.00Nett)

Less: Excess

(S\$ 1,250.00)

Nett Liability

S\$ 57,719.34

(a) – (b) =

(S\$ 27,975.66)

The amount of estimated saving of S\$27,975.66 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

According to the repairer, they declare that SMQ 626B is beyond economical for repair due to foreseen further supplementary or serious damages.

Vehicle Inspected By:



KONG SENG CHEONG  
Licensed Appraiser



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.