



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22001707/Uvf3n2	
			Date: 29/03/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	XE 85U	Veh. Inspected	SJH 9688X
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200681/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	22/02/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA LEXUS ES300H (A)	c.c	2494
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JTHBW1GGX02053162	Colour	BROWN
	Odometer	120749 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	HABILEAD	7 mm
	L/H Front Tyre	215/55 R17	HABILEAD	7 mm
	R/H Rear Tyre	215/55 R17	HABILEAD	7 mm
	L/H Rear Tyre	215/55 R17	HABILEAD	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	22/02/2022	Inspection Date	22/02/2022
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	