

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001708/AQY3Q2**Date:** 26/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00044872102

Claimant Vehicle No : SJT6195H **Insured Vehicle No :** GBJ4361E

Date of Loss: 15/02/2022 Nature of Claim: TP Claim No: SNM22D201187/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT6195H**

Make & Model: TOYOTA PREVIA, 2.4 7-seater (A) Engine No: 2AZH383615

Reg. Date: 22/10/2009 (Man. Year: 2009) Chassis No: JTEGD52M70A017366

Colour: Silver Odometer: 125769 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,752.09	3,211.98	4,540.11	58.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,810.00	1,370.00	43.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,932.09	5,021.98	5,910.11	54.06
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	10,932.09	4,000.00	6,932.09	63.41
+ GST 7.00/7.00% (S\$)	765.25	280.00	485.25	63.41
Nett Amount (S\$)	11,697.34	4,280.00	7,417.34	63.41

INSPECTION

Date of Assignment: 22/02/2022

Date Inspected: 23/02/2022 Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2022)
Parts:	M1-MPV	TOYOTA PREVIA 2.4 7-seater (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT6195H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	862.80 FL	*685.00 FL
2	8		*REAR BUMPER CLIPS	Necessary	46.24 FL	*46.24 FL
3	2		*REAR BUMPER SIDE HOLDER L/R	Necessary	129.80 FL	*129.80 FL
4	2		*REAR BUMPER BRACKET L/R	Not Necessary	151.60 FL	*- FL
5	2		*REAR REFLECTOR LAMP L/R	Not Necessary	162.40 FL	*- FL
6	1		*REAR END PANEL	Dented	874.20 FL	*685.00 FL
7	1		*REAR END PANEL INNER TOP GARNISH	Deformed	380.20 FL	*380.20 FL
8	1		*REAR TYRE PANEL	Repair	789.71 FL	*- FL
9	2		*REAR LAMP ASSY L/R	Not Necessary	1,049.00 FL	*- FL
10	1		*REAR BOOT LID	Dented	1,939.60 FL	*1,549.00 FL
11	1		*REAR BOOT LID WEATHERSTRIP	Not Necessary	375.80 FL	*- FL
12	1		*REAR BOOT LID MECHANISM LOCK	Damaged	590.67 FL	*409.00 FL
13	1		*REAR NO PLATE LAMP	Not Necessary	98.20 FL	*- FL
14	1		*REAR NO PLATE CHROME TRIM MOULDING	Not Necessary	341.20 FL	*- FL
15	2		*REAR BOOT LID DAMPER L/R	Not Necessary	556.20 FL	*- FL
16	1		*REAR WINDSCREEN MOULDING	Necessary	78.40 FL	*78.40 FL
17	1		*REAR BOOT LID INNER HANDLE	Not Necessary	59.20 FL	*- FL
18	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	551.10 FL	*- FL
19	1		*REAR WIPER MOTOR	Not Necessary	779.80 FL	*- FL
20	1		*REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
21	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,206.12	4,202.64
- List Item Discount on L Items 25.00/25.00% (\$)	2,454.03	990.66
Total Parts (\$)	7,752.09	3,211.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REARANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	80.00	30.00
2	TO REMOVE ,REPLACE REAR WINDSCREEN	New	200.00	120.00
3	TO REMOVE ,REINSTAL UPHOLSTERY INNER TRIM GARNISHES	New	200.00	60.00
4	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODY WORKS WHERE CONSISTENT TO THE ACCIDENT	New	1,500.00	800.00
5	TO PUTTY AND RESPRAY PAINTING ON THE AFFECTED AREA	New	1,200.00	800.00
Gross Labour Cost (\$\$)			3,180.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >