

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22001713/ANY3E2

Date: 07/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00020762101
Claimant Vehicle No : GBG1031T **Insured Vehicle No :** GBK2633D
Date of Loss: 10/02/2022 Nature of Claim: TP Claim No: SNM22D201097/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG1031T**
Make & Model: NISSAN NV350, 2.5 PANEL VAN 5MT 5DR EURO V (M) Engine No: YD25415918A
Reg. Date: 31/05/2017 (Man. Year: 2016) Chassis No: JN1MC2E26Z0007941
Colour: Grey Odometer: 169497 km
Engine Capacity: 2488 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
Front Left Side: Achilles 6 mm Rear Left Side: Achilles 6 mm
Front Right Side: Achilles 6 mm Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,214.58	880.69	5,333.89	85.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,190.00	780.00	2,410.00	75.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,404.58	1,660.69	7,743.89	82.34
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	9,404.58	1,300.00	8,104.58	86.18

INSPECTION

Date of Assignment: 22/02/2022
Date Inspected: 22/02/2022 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jul 2022)		
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5MT 5DR EURO V (M) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for GBG1031T)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	688.70 FL	*688.70 FL
2	1		*REAR BUMPER STEP PANEL	Not Necessary	269.60 FL	*- FL
3	1		*REAR BUMPER SIDE HOLDER CLIP (6PCS)	Necessary	45.00 FL	*20.00 FL
4	1		*TAIL GATE	Not Necessary	1,816.70 FL	*- FL
5	1		*TAIL GATE CATCH	Not Necessary	31.80 FL	*- FL
6	2		*TAIL GATE SIDE STOPPER	Not Necessary	38.00 FL	*- FL
7	2		*TAILGATE DAMPER	Not Necessary	350.80 FL	*- FL
8	1		*TAIL GATE OUTER MOULDING	Not Necessary	463.90 FL	*- FL
9	1		*TAIL GATE EMBLEM NV350	Not Necessary	89.70 FL	*- FL
10	1		*TAIL GATE EMBLEM URVAN	Not Necessary	78.90 FL	*- FL
11	1		*TAIL GATE WEATHER STRIP	Not Necessary	175.30 FL	*- FL
12	1		*TAIL GATE INNER LOCK	Not Necessary	394.10 FL	*- FL
13	1		*TAIL LAMP LH	Cracked	225.40 FL	*225.40 FL
14	1		*REAR END PANEL (OUTER)	Not Necessary	461.60 FL	*- FL
15	1		*REAR END PANEL (INNER)	Not Necessary	986.70 FL	*- FL
16	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
17	1		*SET TAIL GATE INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
18	1		*SET TAIL GATE OUTER MOULDING CLIP	Not Necessary	30.00 FS	*- FS
19	1		*TAIL GATE STICKER 70KM/H	Not Necessary	40.00 FS	*- FS
20	1		*TAIL GATE WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
21	1		*TAIL GATE WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
22	1		*SET TAIL LAMP CLIP	Necessary	30.00 FS	*10.00 FS
23	1		*REAR END PANEL (OUTER) SEALANT	Not Necessary	150.00 FS	*- FS
24	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,826.20	974.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	611.62	93.41
Total Parts (\$\$)	6,214.58	880.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,200.00	300.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	400.00
3	TUFF COAT	New	250.00	30.00
4	TRANSFER TAILGATE MECHANISM	New	80.00	0.00
5	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	0.00
6	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
7	REMOVE AND REFIX REAR REVERSE SENSOR	New	80.00	50.00
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			3,190.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >