

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001715/UQY3N2**Date:** 04/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00035642103

Claimant Vehicle No : SJH1436J **Insured Vehicle No :** YL5312H

Date of Loss: 18/02/2022 Nature of Claim: TP Claim No: SNM22D201299/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH1436J**

Make & Model: HONDA ODYSSEY, 2.4 (A) Engine No: K24A65003840

Reg. Date: 28/07/2008 (Man. Year: 2008) Chassis No: JHMRB18508C203840

Colour: Purple Odometer: 154681 km

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,370.00	1,907.12	1,462.88	43.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	480.00	500.00	51.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,350.00	2,387.12	1,962.88	45.12
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	4,350.00	1,900.00	2,450.00	56.32
+ GST 7.00/7.00% (S\$)	304.50	133.00	171.50	56.32
Nett Amount (S\$)	4,654.50	2,033.00	2,621.50	56.32

INSPECTION

Date of Assignment: 22/02/2022

Date Inspected: 23/02/2022 Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2022)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH1436J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented/Deformed	850.00 FL	*801.90 FL
2	1		*FRONT BUMPER REINFORCEMENT	Repair	350.00 FL	*- FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FL	*40.00 FL
4	1		*FRONT BUMPER LOWER CENTER AIR GRILLE	Not Necessary	205.00 FL	*- FL
5	2		*HEAD LAMP O/S & N/S	Holder Cracked	1,780.00 FL	*1,542.00 FL
6	1		*RADIATOR GRILLE	Serviceable	380.00 FL	*- FL
7	1		*RADIATOR GRILLE CHROME MOULDING TOP	Not Necessary	130.00 FL	*- FL
8	1		*FRONT NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
9	1		*SET FRONT BUMPER SENSOR	Not Necessary	300.00 FS	*- FS
					Sub Total (\$\$)	4,125.00 2,383.90
					- List Item Discount on L Items 20.00/20.00% (\$\$)	755.00 476.78
					Total Parts (\$\$)	3,370.00 1,907.12

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING FRONT OF THE AFFECTED PORTION	New	400.00	200.00
2	PANEL BEATING,KNOCKING AND STRAIGHTEN FRONT THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	400.00	220.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00	20.00
4	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	40.00
Gross Labour Cost (S\$)			980.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >