



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:GARNET			Ref: CC4/ASM22001720/Apa3q2 Date: 20/09/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLV 6453D	Veh. Inspected	SMG 77M
	Policy No.	GA503870	Coverage (\$)	0.00
	Claim No.	S2M03TWT	Excess (\$)	0.00
	Assign From		Assign Date	22/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	LEXUS ES300H	c.c	2487
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTHB21B1902004940	Colour	WHITE
	Odometer	88825 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/45 R18	DUNLOP	6 mm
	L/H Front Tyre	235/45 R18	DUNLOP	6 mm
	R/H Rear Tyre	235/45 R18	DUNLOP	6 mm
	L/H Rear Tyre	235/45 R18	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/02/2022	Inspection Date	23/02/2022
	Survey held at	AUTOBACS CAR CARE (S) PTE LTD 8 KAKI BUKIT AVENUE 4 #08-40/45/46 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	