

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22001725/AVY3E2

Date: 09/05/2022

REFERENCE

Insured/Claimant:	ANG SENG PING	Policy No:	2100476375	
Date of Loss:	19/02/2022	Nature of Claim:	OD	Claim No: 6486128749SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE729M		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)	Engine No:	CZC540632
Reg. Date:	26/07/2016 (Man. Year: 2016)	Chassis No:	WAUZZZ8V7G1090069
Colour:	Grey	Odometer:	91990 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$64,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,000.00	2,918.80	10,081.20	77.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,202.00	1,602.00	1,600.00	49.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,202.00	4,520.80	11,681.20	72.10
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	15,902.00	4,220.80	11,681.20	73.46
+ GST 7.00/7.00% (S\$)	1,113.14	295.46	817.68	73.46
Nett Amount (S\$)	17,015.14	4,516.26	12,498.88	73.46

INSPECTION

Date of Assignment:	23/02/2022		
Date Inspected:	22/02/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	2		*FRONT BUMPER TRIM COVER - LH / RH	Not Necessary	364.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	175.00 FS	*- FS
5	4		*FRONT BUMPER PULL STRAP - LOWER	Not Necessary	231.00 FS	*- FS
6	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	86.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	N/S Missing	244.00 FS	*97.20 FS
8	1		*RADIATOR GRILLE	Cracked	765.00 FS	*612.00 FS
9	1		*RADIATOR GRILLE UPPER COVER	Not Necessary	109.00 FS	*- FS
10	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
11	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	847.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	154.00 FS	*122.80 FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Cracked	63.00 FS	*49.84 FS
15	2		*HORN - LH / RH	Not Necessary	426.00 FS	*- FS
16	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	183.00 FS	*- FS
17	2		*HEADLIGHT - LH / RH	Not Necessary	5,620.00 FS	*- FS
18	2		*LIFT CYLINDER - LH / RH	Not Necessary	422.00 FS	*- FS
19	1		*LIFT CYLINDER HOSE	Not Necessary	204.00 FS	*- FS
20	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	56.00 FS	*- FS
21	1		*RADIATOR SEAL - RH OUTER	Not Necessary	9.00 FS	*- FS
22	1		*RADIATOR AIR GUIDE - UPPER CENTER	Not Necessary	14.00 FS	*- FS
23	1		*BONNET CATCH HOOK	Bent	71.00 FS	*56.32 FS
24	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
25	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 13,000.00 2,918.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULE	New	700.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER	New	900.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,202.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >