

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22001726/AVY3N2**Date:** 25/04/2022**REFERENCE**

Insured/Claimant:	SENG KOK ANN IVAN	Policy No:	1800152116	
Date of Loss:	13/02/2022	Nature of Claim:	OD	Claim No: 0074782135SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU8789P		
Make & Model:	AUDI A3 SPORTBACK, 1.0 TFSI S TRONIC (LED) (A)	Engine No:	CHZB21941
Reg. Date:	28/12/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V1KA010998
Colour:	Grey	Odometer:	51132 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$92,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,374.00	4,132.56	13,241.44	76.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,352.00	2,292.00	4,060.00	63.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,726.00	6,424.56	17,301.44	72.92
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	23,426.00	6,124.56	17,301.44	73.86
+ GST 7.00/7.00% (S\$)	1,639.82	428.72	1,211.10	73.86
Nett Amount (S\$)	25,065.82	6,553.28	18,512.54	73.86

INSPECTION

Date of Assignment:	23/02/2022	
Date Inspected:	22/02/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,146.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	86.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	179.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	332.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT-LH/RH	Not Necessary	636.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	210.00 FS	*168.00 FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	210.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	211.00 FS	*- FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	847.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	136.00 FS	*- FS
13	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
14	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
15	1		*HORN-LH	Not Necessary	213.00 FS	*- FS
16	1		*BONNET	Dented	3,370.00 FS	*2,696.00 FS
17	1		*BONNET ATTACHMENT PARTS	Not Necessary	172.00 FS	*- FS
18	1		*BONNET EDGE PROTECTION	Necessary	31.00 FS	*24.72 FS
19	1		*BONNET STRIKER-LH	Not Necessary	123.00 FS	*- FS
20	1		*BONNET MICRO-SWITCH-LH	Not Necessary	228.00 FS	*- FS
21	1		*BONNET BOWDEN CABLE-CENTER	Not Necessary	64.00 FS	*- FS
22	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
23	1		*BONNET CATCH HOOK-LOWER	Not Necessary	71.00 FS	*- FS
24	1		*BONNET CATCH HOOK-UPPER	Not Necessary	100.00 FS	*- FS
25	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	183.00 FS	*- FS
26	1		*HEADLIGHT-LH	Not Necessary	5,455.00 FS	*- FS
27	1		*LIFT CYLINDER-LH	Not Necessary	156.00 FS	*- FS
28	1		*LIFT CYLINDER HOSE	Not Necessary	78.00 FS	*- FS
29	2		*RADIATOR AIR GUIDE-LH/RH	Not Necessary	56.00 FS	*- FS
30	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
31	1		*RADIATOR SEAL-RH OUTER	Not Necessary	9.00 FS	*- FS
32	1		*RADIATOR AIR GUIDE-UPPER CENTER	Not Necessary	14.00 FS	*- FS
33	1		*FRONT NO PLATE	Dented	100.00 FS	*100.00 FS
34	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 17,374.00 4,132.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND LHS HEADLIGHT.TO REPAIR LHS FRONT FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
4	TO RESPRAY FRONT BUMPER,BONNET AND LHS FRONT FENDER	New	3,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,352.00	2,292.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >