



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 3608P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (WCP)	DEFORMED / TORN	320.00	320.00
10	FRONT BUMPER CLIPS @\$1.50 (WCP)	NECESSARY	15.00	15.00
1	N/S FRONT BUMPER SENSOR (WCP)	SERVICEABLE	140.00	-
1	N/S FOG LAMP CHROME MOULDING (WCP)	NOT NECESSARY	55.00	-
1	N/S HEADLAMP (WCP)	NOT NECESSARY	1,800.00	-
	COST PLUS 10%		233.00	33.50
			2,563.00	368.50
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING FRONT BUMPER, FRONT FENDER OF THE AFFECTED PORTION.		700.00	400.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		450.00	200.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		80.00	40.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		100.00	20.00
			1,330.00	660.00
	GRAND TOTAL		3,893.00	1,028.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			800.00

Report Ref No. CS/AIS22001729/Uvf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.