

(02/11/13) Wef
ASS. REC. BY: Marcus

REF:

CS/AIS22001729/Urf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMP 3608P

at Workshop m/s Turkmen

of _____

Insured: SJQ 8788A

Policy No. _____

Claims No. 2022 22003948SL

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: £ 85k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: LIA 53783

Date / Time Action / Instruction

SMP 3608P 7881

Rep 15h

Veh No: SMP 3608P

Yr Regn: 17/3/16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Lexus

ES250

C.C. 2494

Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 107 499

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTHBJ 166 702 09 114

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 10/2/22

D.O.I. 23/2/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 28/2/22-typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

Add Fee: _____

☐

: Site Insp (\$ _____)

) \$ + RS. _____

☐

: Interview (\$ _____)

) Photos _____

☐

: Tech. Invs (\$ _____)

) Others _____

☐

: Weekend (\$ _____)

) _____

Report Format: TP

Lump Sum / +B: (\$ 800)

TOTAL

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-approved
- is subject to final approval from Insurance Company



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel: 68585151 (24 Hours) Fax: 68580877

GST Regn. No. : M2-8922054-2

Allianz Insured's Veh No : SJQ8788A

Date of Accident : 10 February 2022

Acknowledged by Repairer

Signature:

Mr Alvin Cheng Fook Loy @ Alvin Cheng Fei Long

Date : 22 February 2022

Estimate To Repair SMP3608P - Toyota LEXUS ES250 LUXURY AUTO

Chassis No : JTHBJ1GG702091141

S/No	Quantity	Description	Amount
SPECIAL NETT ITEMS			
01	1 pc	front bumper	\$ 320.00
02	10 pcs	front bumper clips @ \$1.50	\$ 15.00
03	1 pc	n/s front bumper sensor	\$ 140.00
04	1 pc	n/s fog lamp chrome moulding	\$ 55.00
05	1 pc	n/s headlamp	\$ 1,800.00
			\$ 2,330.00
LABOUR & MISC. CHARGES			
01		Putty and spray painting front bumper, front fender of the affected portion.	\$ 700.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 450.00
03		To reinstall of rear bumper parking sensor.	\$ 80.00
04		To check electrical lighting concerned.	\$ 100.00
			\$ 1,330.00
		Total	\$ 3,660.00

not approved
L/s \$ 800
2 days
23/2/22
whenever after repair

P- 335
102
P- 368.50
L- 660.00
1028.50
203
822