



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 4194A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED / DEFORMED	1,750.00	1,392.35
1	FRONT BUMPER FOAM	NOT NECESSARY	235.00	-
1	FRONT BUMPER LOGO	NECESSARY	89.80	89.80
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	555.00	-
2	FRONT GRILLE @1856.00	O/S CRACKED	3,712.00	106.80
1	O/S HEADLAMP	CRACKED	2,989.00	2,989.00
1	O/S HEADLAMP BRACKET	NOT NECESSARY	85.00	-
1	AIR GUIDE - OUTER	NOT NECESSARY	83.00	-
1	AIR GUIDE - INNER	NOT NECESSARY	83.00	-
2	FRONT PARKING SENSOR @235.00	SERVICEABLE	470.00	-
	LESS 10% DISCOUNT		-1,005.18	-457.80
			9,046.62	4,120.15
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	DENTED	50.00	40.00
			50.00	40.00
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		80.00	20.00
	USING ONBOARD SCAN TOOL (OBD) PERFORM FULL ENGINE DIAGNOSTIC CHECK, TO CONFIGURE AND CLEAR, RESET SRS SERVICE LIGHT.		380.00	50.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		500.00	200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		400.00	200.00
			1,360.00	470.00
	GRAND TOTAL		10,456.62	4,630.15



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00
---	--	--	-----------------

Report Ref No. CS/AGI22001730/Utf3z2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.