

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22001732/Vqy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	15/03/2022		
	ATTN: NG STACE	Y		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	EV 2211U	Veh. Inspected	ł	FBA 886G	
	Policy No.	GA495355	Coverage (\$)		0.00	
	Claim No.	S2M03TKZ	Excess (\$)		0.00	
	Assign From	NG STACEY	Assign Date		23/02/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA CB400	c.c		399	
	Engine No.	HIDDEN	Year of Reg.		2006	
	Chassis No.	JH2NC39955M100022	Colour		WHITE	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	120/60Z R17	PIRELLI		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	120/60Z R17	PIRELLI		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.					
5.	General Information					
	Accident Date	16/02/2022	Inspect Date /	Time	23/02/2022 (04:00 PM)	
	Survey held at WING FUAT TRADING CO					
	BLK 3020A UBI ROAD 1 #01-37 SINGAPORE 408714					
5a.	. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000					
5b. Estimate Days of Repair						
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM22001732/Vqy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

Tu

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser