

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22001734/EQY3E2

Date: 18/05/2022

REFERENCE

Insured/Claimant: LAU LIANG PENG Policy No: DMPCSNW00126442100

Date of Loss: 18/02/2022 Nature of Claim: OD Claim No: SNM22D201256/C01/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU1635Y**

Make & Model: VOLVO XC40, 2.0 T4 MOMENTUM (A)

Engine No: B4204T473260739

Reg. Date: 30/07/2020 (Man. Year: 2019)

Chassis No: YV1XZACADL2207486

Colour: White

Odometer: 11347 km

Engine Capacity: 1969 cc

Market Value/New Car Price: S\$154,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Pirelli 5 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm

Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	57,224.59	39,910.68	17,313.91	30.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	26,260.00	19,355.00	6,905.00	26.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	83,484.59	59,265.68	24,218.91	29.01
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	82,734.59	58,515.68	24,218.91	29.27
+ GST 7.00/7.00% (S\$)	5,791.42	4,096.10	1,695.32	29.27
Nett Amount (S\$)	88,526.01	62,611.78	25,914.23	29.27

INSPECTION

Date of Assignment: 23/02/2022

Date Inspected: 24/02/2022 Inspected At:

Wearnes Automotive Pte Ltd (Alexandra Road)
249 Alexandra Road
Singapore 159935

Estimated Period of Repair: 17.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 May 2022)	
Parts:	N/A	VOLVO XC40 2.0 T4 MOMENTUM (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU1635Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT XC4	Broken	2,199.70 FS	*1,979.73 FS
2	1		*RADIATOR GRILLE XC40	Cut	1,012.60 FS	*911.34 FS
3	1		*BUMPER CARRIER FRT L	Missing	30.50 FS	*27.45 FS
4	1		*BUMPER CARRIER FRT R	Not Necessary	30.50 FS	*- FS
5	1		*V032136051/BUMPER UN	Broken	177.80 FS	*160.02 FS
6	1		*BUMPER FOAM FRT ALL	Broken	286.90 FS	*258.21 FS
7	1		*BUMPER SPOILER FRT A	Broken	562.20 FS	*505.98 FS
8	1		*BUMPER GRILLE LOWER	Not Necessary	152.30 FS	*- FS
9	1		*PROTECTING PLATE FRT	Cut	742.90 FS	*668.61 FS
10	1		*FOG COVER BRACKET LH	Missing	59.30 FS	*53.37 FS
11	1		*FOG COVER BRACKET RH	Not Necessary	59.30 FS	*- FS
12	1		*FOG COVER LH XC40 18	Missing	80.40 FS	*72.36 FS
13	1		*FOG COVER RH XC40 18	Not Necessary	80.40 FS	*- FS
14	1		*NUMBER PLATE RETAINER	Not Necessary	70.50 FS	*- FS
15	1		*EXPANDING NUT XC40 1 (10PCS)	Necessary(2Pcs Only)	63.00 FS	*11.34 FS
16	1		*BUMPER BRACKET FRT L	Necessary	90.90 FS	*81.81 FS
17	1		*BUMPER BRACKET FRT R	Broken	90.90 FS	*81.81 FS
18	10		*BUMPER CLIP S80 07-	Necessary	57.00 FS	*51.30 FS
19	1		*BUMPER INSTALLING MT	Necessary	96.50 FS	*86.85 FS
20	10		*WIPER GRILLE CLIP XC	Necessary	83.00 FS	*74.70 FS
21	10		*BLIND RIVET 4.0*21 P	Necessary	47.00 FS	*42.30 FS
22	10		*BUMPER CLIP 8X8,5	Necessary	78.00 FS	*70.20 FS
23	1		*WHEELARCH FRT LH XC4	Broken	240.90 FS	*216.81 FS
24	1		*AIR DEFLECTOR LH XC4	Missing	77.30 FS	*69.57 FS
25	1		*PROTECTION LH	Not Necessary	68.20 FS	*- FS
26	1		*BONNET FRT XC40 18-	Dented	2,580.50 FS	*2,322.45 FS
27	1		*V031356752/BONNET HI	Bent	318.10 FS	*286.29 FS
28	1		*V031356753/BONNET HI	Bent	318.10 FS	*286.29 FS
29	1		*BONNET STRUT XC40 18	Not Necessary	250.00 FS	*- FS
30	1		*SAFETY CATCH XC40 18	Not Necessary	179.60 FS	*- FS
31	1		*BONNET LOCK LH XC40	Bent	218.10 FS	*196.29 FS
32	1		*BONNET LOCK RH XC40	Not Necessary	218.10 FS	*- FS
33	1		*WIRE BOX REAR	Not Necessary	129.50 FS	*- FS
34	1		*BONNET CABLE XC40 21	Not Necessary	129.50 FS	*- FS
35	1		*TRIM COVER FENDER LH	Missing	159.10 FS	*143.19 FS
36	10		*CLIP	Necessary	59.00 FS	*53.10 FS
37	1		*FENDER PANEL FRT LH	Dented	1,364.70 FS	*1,228.23 FS
38	1		*FENDER CARRIER BRACK	Broken	30.50 FS	*27.45 FS
39	1		*V032234761/FENDER CA	Broken	173.40 FS	*156.06 FS
40	1		*V032297849/BUMPER RA	Bent	1,481.20 FS	*1,333.08 FS
41	1		*BRACKET BUMPER BEAM	Bent	168.20 FS	*151.38 FS
42	1		*BRACKET BUMPER BEAM	Bent	168.20 FS	*151.38 FS
43	1		*BRACKET BEAM FRT XC4	Bent	102.30 FS	*92.07 FS
44	2		*FLANGE SCREW M12X40	Necessary	9.00 FS	*8.10 FS
45	1		*HEADLAMP LED LH XC40	Broken	2,260.60 FS	*2,034.54 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*HEADLAMP CONTROL UNI	Not Necessary	577.40 FS	*- FS
47	1		**S* HCM RELOAD XC40	Necessary	105.70 FS	*95.13 FS
48	1		*PARK SENSOR FRT / REAR (4PCS)	Broken (1Pc Only)	820.80 FS	*184.68 FS
49	1		*CABLE HARNESS LH XC4	Not Necessary	1,743.40 FS	*- FS
50	1		*PARK CABLE HARNESS F	Torn	140.40 FS	*126.36 FS
51	1		*ALLOY RIM 18 5-SPOKE	Cut	1,363.80 FS	*1,227.42 FS
52	1		*KNUCKLE ARM LH XC40	Not Necessary	889.10 FS	*- FS
53	1		*V032221265/HUB KIT F	Not Necessary	548.70 FS	*- FS
54	1		*CONTROL ARM LOWER LH	Not Necessary	327.20 FS	*- FS
55	1		*FLANGE SCREW M12X75	Not Necessary	5.90 FS	*- FS
56	1		*FLANGE SCREW M12X60	Not Necessary	5.90 FS	*- FS
57	1		*SEMS SCREW M14X105	Not Necessary	9.50 FS	*- FS
58	1		*SEMS SCREW M14X80	Not Necessary	5.90 FS	*- FS
59	1		*SUBFRAME FRT XC40 18	Not Necessary	2,343.00 FS	*- FS
60	1		*CROSS MEMBER FRT XC4	Not Necessary	259.30 FS	*- FS
61	1		*STAY LH CROSSMEMBER	Not Necessary	27.90 FS	*- FS
62	1		*STAY RH CROSSMEMBER	Not Necessary	27.90 FS	*- FS
63	1		*V036011625/STEERING	Not Necessary	2,346.40 FS	*- FS
64	1		**S* PSCM RELOAD XC40	Not Necessary	109.90 FS	*- FS
65	1		*ABSORBER MTG FRT XC4	Not Necessary	123.00 FS	*- FS
66	1		*BEARING ABSORBER XC4	Not Necessary	123.00 FS	*- FS
67	1		*BUMP STOP XC40 18-	Not Necessary	64.90 FS	*- FS
68	1		*PROTECTING BELLOWS	Not Necessary	18.30 FS	*- FS
69	1		*ABSORBER FRT LH XC40	Not Necessary	392.10 FS	*- FS
70	2		*V032221271/LINK ROD	Not Necessary	319.40 FS	*- FS
71	1		*CMP SENSOR FRT LH XC	Not Necessary	315.10 FS	*- FS
72	1		*ABS SENSOR FRT / REAR	Not Necessary	224.60 FS	*- FS
73	1		*DASHBOARD XC40 18-	Broken	2,076.40 FS	*1,868.76 FS
74	1		*CONTROL UNIT SRS XC4	Necessary	2,103.70 FS	*1,893.33 FS
75	1		**S* SRS RELOAD XC40	Necessary	152.20 FS	*136.98 FS
76	1		**E* AIRBAG MODULE ST	Broken	2,998.80 FS	*2,698.92 FS
77	1		**E* AIRBAG MODULE PA	Broken	3,180.50 FS	*2,862.45 FS
78	1		**E* AIRBAG MODULE KN	Broken	2,362.60 FS	*2,126.34 FS
79	2		*SENSOR AIRBAG FRT S6	Necessary	863.40 FS	*777.06 FS
80	1		**E* SEAT BELT FRT LH	Jammed	1,363.10 FS	*1,226.79 FS
81	1		*V031462121/*E* SEAT	Jammed	1,458.60 FS	*1,312.74 FS
82	2		**E* SEAT BELT REAR L	Necessary	2,789.80 FS	*2,510.82 FS
83	1		**E* SEAT BELT REAR C	Necessary	1,394.90 FS	*1,255.41 FS
84	1		*IU STICKER	Necessary	6.30 FS	*5.67 FS
85	1		*WINDSCREEN FRT ALL X	Broken	1,740.60 FS	*1,566.54 FS
86	1		**D* PRIMER GLASS & P	Necessary	43.30 FS	*38.97 FS
87	1		**D* GLASS CLEANER H	Necessary	82.40 FS	*74.16 FS
88	2		**D* WINDSCREEN SEALA	Necessary	328.80 FS	*295.92 FS
89	1		*V031652847/RAIN SENS	Necessary	384.50 FS	*346.05 FS
90	10		*A PILLAR CLIP WHITE	Necessary	183.00 FS	*164.70 FS
91	2		*A PILLAR CLIP PINK S	Necessary	25.60 FS	*23.04 FS
92	1		*FENDER FOAMBLOCK LH	Missing	101.60 FS	*91.44 FS
93	1		*V031651852/PANEL INS	Bent	50.00 FS	*45.00 FS
94	1		*SIDE PANEL FRT LH XC	Not Necessary	170.50 FS	*- FS
95	1		*SIDE PANEL BRACKET L	Dented	159.10 FS	*143.19 FS
96	1		*SIDE PANEL BRACKET L	Dented	65.70 FS	*59.13 FS
97	1		*V032234760/FRONT SEC	Dented	224.50 FS	*202.05 FS
98	1		*SIDE PANEL CATCH XC4	Not Necessary	143.20 FS	*- FS
99	1		*CLIP KIT LH PARCEL S	Necessary	5.22 FS	*5.22 FS
100	1		*HORN LH XC40 18-	Broken	79.20 FS	*79.20 FS
101	1		*V032226764/ENGINE UN	Broken	240.57 FS	*240.57 FS
102	1		*BONNET LOCK BRACE LH	Bent	81.72 FS	*81.72 FS
103	1		*BONNET LOCK BRAKE RH	Bent	81.72 FS	*81.72 FS
104	1		*BRACKET FENDER LH XC	Dented	127.98 FS	*127.98 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
105	1		*BUMPER CARRIER FRT R	Broken	28.89 FS	*28.89 FS
106	1		*BATT 10AH170A UP 242	Crushed	229.05 FS	*229.05 FS
107	1		*BRACKET BATTERY XC40	Necessary	56.70 FS	*56.70 FS
108	1		*MEGA FUSE 70A XC60 1	Necessary	3.87 FS	*3.87 FS
109	1		*RETAINER FUSE HOLDER	Broken	64.98 FS	*64.98 FS
110	1		*BUSBAR	Broken	144.63 FS	*144.63 FS
111	1		*SIDE PANEL BRACKET R	Dented	150.39 FS	*150.39 FS
112	1		*SOUND ABSORBER	Crushed	628.92 FS	*628.92 FS
113	1		*INSULATING MAT	Broken	110.52 FS	*110.52 FS
114	1		*SIDE PANEL LH	Dented	167.94 FS	*167.94 FS
115	2		*V009437654/*D* VOLVO	Necessary	100.80 FS	*100.80 FS
116	1		*SIDE PANEL FRT RH XC	Dented	161.19 FS	*161.19 FS
117	2		*FLANGE SCREW M12X40	Necessary	8.64 FS	*8.64 FS
118	1		*BRACE SUPPORT BSTTER	Necessary	11.16 FS	*11.16 FS
119	1		*WIDENER FRT LH XC40	Missing	193.20 FS	*173.88 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	57,224.59	39,910.68
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRT BONNET, FRT BUMPER, FRT GRILL, FRT LH HEADLAMP, FRONT LH FENDER, INNER PANEL, LH DOOR, LH WHEEL ARCH , TOP PANEL, ETC	New	7,650.00	5,100.00
2	TO PUTTY SPRAY PAINT ON FRT BONNET, FRT BUMPER, FRT LH FENDER, FRT LH INNER PANEL, FRT LH DOOR, LH A PILLAR, LH CHASSIS, ETC	New	6,000.00	4,875.00
3	TO VACUUM & TOP UP A/C GAS	New	350.00	0.00
4	TO REPLACE FRONT WINDSCREEN	New	850.00	850.00
5	TO REPLACE FRONT DASHBOARD, LH & RH AIR BAG, KNEE AIR BAG, ETC	New	5,760.00	4,320.00
6	TO REPLACE ALL SEAT BELTS, SRS CONTROL MODULES INCLUDE PROGRAMMING, ETC	New	4,320.00	2,880.00
7	TO REPLACE FRONT LH RIM	New	50.00	50.00
8	COMPUTERISED WHEEL ALIGNMENT	New	280.00	280.00
9	TO INSTALL FRONT WINDSCREEN FI	New	280.00	280.00
10	TO FOCUS HEADLAMP	New	180.00	180.00
11	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES	New	540.00	540.00
Gross Labour Cost (\$\$)			26,260.00	19,355.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >