

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22001737/BVY3E2

**Date:** 14/04/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00142712102  
Claimant Vehicle No: SFS5778K Insured Vehicle No: XE1848D  
Date of Loss: 20/01/2022 Nature of Claim: TP Claim No: SNM22D200543/C02/TANKW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFS5778K  
Make & Model: TOYOTA COROLLA ALTIS, 1.6 Classic (A) Engine No: 1ZRY137302  
Reg. Date: 05/03/2015 (Man. Year: 2014) Chassis No: MR053REH104523609  
Colour: White Odometer: 148817 km  
Engine Capacity: 1598 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: Continental 4 mm Rear Left Side: Continental 4 mm  
Front Right Side: Continental 4 mm Rear Right Side: Continental 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,534.36	5,102.94	10,431.42	67.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,490.00	1,980.00	3,510.00	63.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>21,024.36</b>	<b>7,082.94</b>	<b>13,941.42</b>	<b>66.31</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,650.00</b>		
<b>(S\$)</b>	21,024.36	5,650.00	15,374.36	73.13
<b>+ GST 7.00/7.00% (S\$)</b>	1,471.71	395.50	1,076.21	73.13
<b>Nett Amount (S\$)</b>	<b>22,496.07</b>	<b>6,045.50</b>	<b>16,450.57</b>	<b>73.13</b>

### INSPECTION

Date of Assignment: 23/02/2022  
Date Inspected: 25/02/2022 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)  
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit  
Singapore 415875  
Estimated Period of Repair: 7.0 days

**Adjuster:** Lim Teow Guan

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2022)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 Classic (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFS5778K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Damaged	581.45 FL	*- FL
2	1		*SET FRONT BUMPER CLIPS	Not Necessary	60.00 FL	*- FL
3	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	132.10 FL	*- FL
4	1		*RH HEADLAMP ASSY	Not Damaged	861.00 FL	*- FL
5	1		*RH FRONT FENDER	Not Damaged	656.00 FL	*- FL
6	1		*RH FRONT FENDER EMBLEM	Not Necessary	54.00 FL	*- FL
7	1		*RH FRONT FENDER SPLASH SHIELD	Not Damaged	200.90 FL	*- FL
8	1		*SET RH FRONT FENDER SPLASH SHIELD CLIPS	Not Damaged	55.00 FL	*- FL
9	1		*RH FRONT SPORT RIM (ORIGINAL)	Not Damaged	1,644.00 FL	*- FL
10	1		*RH FRONT LOWER ARM	Not Damaged	602.70 FL	*- FL
11	1		*RH FRONT KNUCKLE ARM	Not Damaged	521.20 FL	*- FL
12	1		*RH FRONT SHOCK ABSORBER	Not Damaged	398.10 FL	*- FL
13	1		*RH FRONT WHEEL BEARING	Not Damaged	95.70 FL	*- FL
14	1		*RH FRONT TIE ROD END	Not Damaged	93.20 FL	*- FL
15	1		*RH SIDE MIRROR COVER	Cut	1,257.70 FL	*108.60 FL
16	1		*RH FRONT DOOR	Dented	1,079.60 FL	*1,079.60 FL
17	1		*RH FRONT DOOR FRAME BLACK STICKER	Necessary	75.00 FL	*59.60 FL
18	1		*RH FRONT DOOR RUBBER WEATHERSTRIP	Necessary	191.70 FL	*148.00 FL
19	1		*RH FRONT DOOR INNER TRIM BOARD	Not Damaged	903.00 FL	*- FL
20	1		*SET RH FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	60.00 FL	*- FL
21	1		*RH REAR DOOR	Dented	1,211.70 FL	*1,112.10 FL
22	1		*RH REAR DOOR FRAME BLACK STICKER	Necessary	75.00 FL	*59.60 FL
23	1		*RH REAR DOOR RUBBER WEATHERSTRIP	Necessary	191.70 FL	*148.00 FL
24	1		*RH REAR DOOR INNER TRIM BOARD	Broken	903.00 FL	*672.00 FL
25	1		*SET RH REAR DOOR INNER TRIM BOARD CLIPS	Necessary	60.00 FL	*30.00 FL
26	1		*RH REAR SPORT RIM (ORIGINAL)	Cut	1,644.00 FL	*945.85 FL
27	1		*RH REAR WHEEL BEARING	Jammed	654.10 FL	*450.00 FL
28	1		*RH REAR SHOCK ABSORBER	Not Damaged	296.40 FL	*- FL
29	1		*RH REAR AXLE BEAM	Not Damaged	2,466.20 FL	*- FL
30	1		*REAR WINDSCREEN GLASS RUBBER MOULDING	Necessary	60.80 FL	*60.80 FL
31	1		*RH REAR FENDER	Dented	986.30 FL	*845.10 FL
32	1		*REAR BUMPER	Broken	540.20 FL	*540.20 FL
33	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
34	1		*REAR BUMPER RH SIDE RETAINER	Necessary	132.10 FL	*109.30 FL
35	1		*LH TAILLAMP	Not Necessary	316.80 FL	*- FL
36	1		*RH FRONT TYRE	Not Necessary	380.00 FS	*- FS
37	1		*RH REAR TYRE	Not Necessary	380.00 FS	*- FS
38	1		*BRAKE FLUID	Not Necessary	60.00 FS	*- FS
39	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
40	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*20.00 FS
41	1		*RH FRONT DOOR OUTER HANDLE	Cut	157.25 FL	*157.25 FL
42	1		*RH FRONT DOOR OUTER HANDLE RUBBER GASKET	Necessary	12.00 FL	*12.00 FL
43	1		*RH REAR DOOR OUTER HANDLE	Cut	157.25 FL	*157.25 FL
44	1		*RH REAR DOOR OUTER HANDLE RUBBER GASKET	Cut	12.00 FL	*12.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** 20,399.15 6,787.25

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,600.00	1,000.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,300.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	0.00
5	REFOCUS AND ADJUST HEADLAMPS ASSY	New	60.00	0.00
6	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	350.00	0.00
7	REMOVE AND REPLACE RH FRONT DOOR INNER MECHANISM TO NEW DOOR	New	120.00	0.00
8	REMOVE AND REPLACE RH REAR DOOR INNER MECHANISM TO NEW DOOR	New	120.00	0.00
9	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	450.00	0.00
10	REMOVE AND REINSTALL REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	60.00
11	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
12	REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR	New	200.00	120.00
13	REMOVE AND REINSTALL ROOF LINING, SEATS, SEAT BELTS AND CARPET TO ASSIST REPAIR	New	350.00	0.00
14	LABOUR	New	350.00	0.00
15	SPRAY PAINTING BONNET	New	250.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,490.00</b>	<b>1,980.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >