

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001742/UVY3N2**Date:** 28/03/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00074772104

**Claimant Vehicle  
No :** GBJ7298K**Insured  
Vehicle No :** SKM9525U

Date of Loss: 19/02/2022

Nature of Claim: TP

Claim  
No: SNM22D201298/C02/TANKW**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBJ7298K**

Make &amp; Model: TOYOTA DYNA 150, 3.0 D 5MT (M)

Engine No: 1KD2861326

Reg. Date: 01/08/2019 (Man. Year: 2019)

Chassis No: JTFAT35Y90K213844

Colour: Silver

Odometer: 62022 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195R15	Rear Tyre Size:	155R12(D)
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,702.55	2,958.86	1,743.69	37.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,570.00	910.00	36.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,182.55</b>	<b>4,528.86</b>	<b>2,653.69</b>	<b>36.95</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,600.00</b>		
<b>(\$\$)</b>	7,182.55	3,600.00	3,582.55	49.88
<b>+ GST 7.00/7.00% (\$\$)</b>	502.78	252.00	250.78	49.88
<b>Nett Amount (\$\$)</b>	<b>7,685.33</b>	<b>3,852.00</b>	<b>3,833.33</b>	<b>49.88</b>

**INSPECTION**

Date of Assignment: 23/02/2022

Date Inspected: 23/02/2022 Inspected At:

Precise Auto Services (HQ)  
NO.1 KAKI BUKIT AVE 6 #02-34/36  
Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 23 Mar 2022)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBJ7298K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented/Bent	1,712.80 FL	*1,712.80 FL
2	4		*TAIL GATE HINGES	Not Necessary	647.60 FL	*- FL
3	1		*TAIL GATE STICKER TOYOTA	Necessary	160.75 FL	*160.75 FL
4	1		*TAIL GATE STICKER DYNA	Necessary	68.00 FL	*68.00 FL
5	1		*TAIL GATE SIDE LOCK-RH	Twisted	181.75 FL	*181.75 FL
6	1		*TAIL GATE SIDE LOCK BRACKET	Bent	161.50 FL	*151.10 FL
7	1		*TAIL GATE RUBBER STOPPER	Torn	45.90 FL	*45.90 FL
8	1		*TAIL GATE RUBBER STOPPER BRACKET	Bent	151.50 FL	*151.50 FL
9	1		*TAIL GATE LOWER END MEMBER	Bent	682.40 FL	*682.40 FL
10	1		*TAIL LAMP-RH	Cracked	288.40 FL	*288.40 FL
11	1		*TAIL LAMP BRACKET	Repair	181.70 FL	*- FL
12	2		*REAR NUMBER PLATE LAMP	Not Necessary	242.20 FL	*- FL
13	1		*REAR NUMBER PLATE BRACKET	Bent	182.55 FL	*182.55 FL
14	1		*EXHAUST TAIL PIPE	Repair	788.55 FL	*- FL
15	2		*EXHAUST TAIL PIPE MOUNTING	Not Necessary	127.80 FL	*- FL
16	1		*REAR NUMBER PLATE	Bent	65.00 FS	*20.00 FS
17	1		*SET REVERSE SENSOR	Shorted	380.00 FS	*200.00 FS
18	1		*70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
19	1		*13 PAX STICKER	Necessary	20.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,108.40</b>	<b>3,865.15</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,405.85	906.29
<b>Total Parts (\$\$)</b>	<b>4,702.55</b>	<b>2,958.86</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING SYSTEM	New	80.00	20.00
2	TO TUFF COAT AFFECTED AREAS	New	180.00	60.00
3	TO RESPRAY AFFECTED AREAS	New	950.00	700.00
4	TO REMOVE & REPAIR EXHAUST TAIL PIPE	New	220.00	60.00
5	TO RENEW DAMAGED PARTS,STRAIGHTEN & REPAIR REAR RH SIDE GATE,SIDE GATE LOWER MEMBER & ALIGNED ALL PARTS	New	900.00	680.00
6	TO REMOVE & REFIX REVERSE SENSOR	New	150.00	50.00
<b>Gross Labour Cost (\$)</b>			<b>2,480.00</b>	<b>1,570.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >