7/19/22, 12:59 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG22001744/KEA3Q2

19/07/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100501136 **Claimant Vehicle**

SHD952L Insured Vehicle No: SLL2974X No:

Date of Loss: 20/02/2022 Nature of Claim: TP Claim No: 0171743287SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD952L

Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) Engine No: M9R8839C003254 Reg. Date: 03/07/2017 (Man. Year: 2016) Chassis No: VF1ABL15AUC283507

Odometer: Colour: Metallic White/Red 403934 km

Engine Capacity: 1995 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Sailun 9 mm Rear Left Side: Sailun 9 mm Front Right Side: Sailun 9 mm Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,489.52	1,516.20	3,973.32	72.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,880.00	495.00	7,385.00	93.72
Paintwork Labour	0.00	0.00	0.00 0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,369.52	2,011.20	11,358.32	84.96
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	13,369.52	1,600.00	11,769.52	88.03
+ GST 7.00/7.00% (S\$)	935.87	112.00	823.87	88.03
Nett Amount (S\$)	14,305.39	1,712.00	12,593.39	88.03
+ Loss of Use (3.0 x	S\$50.00/day) (S\$)	150.00		
+ Car Rental (3.0 x S\$81.13/day) (S\$)		243.39		
+ Do	+ Doc/Search Fee (S\$)			
	Nett Liability (S\$)			

INSPECTION

Date of Assignment: 22/02/2022

Trans-cab Auto Services Pte Ltd Date Inspected: 22/02/2022 Inspected At: No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

t No. Particulars	Condition	Repairer's	Amount
*BUMPER COVER REAR	Buckled / Cracked	561.70 FL	*561.70 FL
*BUMPER LOWER REAR	Dented / Cut	411.90 FL	*411.90 FL
*BUMPER REFLECTOR LH	Cracked	16.60 FL	*16.60 FL
*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*-FL
*BUMPER BRACKET SIDE RH REAR	Repair	82.10 FL	*- FL
*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*-FL
*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
*BOOT REAR	Repair	1,677.20 FL	*- FL
*BOOT HINGE LH	Repair	254.20 FL	*- FL
*BOOT HINGE RH	Repair	254.20 FL	*-FL
*SET PARKING AID	Serviceable	700.00 FS	*- FS
*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS
*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS
*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
*SET BUMPER LOWER REAR CLIP S=SpcNett. L=ListItemDisc.	Necessary	66.00 FS	*66.00 FS
o-oponett. L-Listiteriibisc.	Sub Total (S\$)	6,000.36	1,670.00
- List Item Discount on L Items 10.00/10.00% (S\$)			153.80
	Total Parts (S\$)	5,489.52	1,516.20
		- List Item Discount on L Items 10.00/10.00% (S\$)	- List Item Discount on L Items 10.00/10.00% (S\$) 510.84 Total Parts (S\$) 5,489.52

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New -	3,000.00	200.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
6	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	N ew	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.) New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
	Gross Labour	r Cost (S\$)	7,880.00	495.00

Report was unsubmitted during this print-out. < END OF ESTIMATES >