

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001749/TQY3M4**Date:** 02/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00054562109

Claimant Vehicle No : CB8256E **Insured Vehicle No :** GY1035D

Date of Loss: 19/02/2022 Nature of Claim: TP Claim No: SNM22D201275/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **CB8256E**

Make & Model: TOYOTA HIACE, 2.8 D GL (A) Engine No: 1GD8513323

Reg. Date: 25/02/2020 (Man. Year: 2019) Chassis No: GDH2111003758

Colour: Purple Odometer: 88931 km

Engine Capacity: 2754 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/70 R15 Rear Tyre Size: 195/70 R15

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,677.50	1,987.55	10,689.95	84.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,760.00	2,400.00	4,360.00	64.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,437.50	4,387.55	15,049.95	77.43
Approved Total (Overridden) (\$\$)		3,500.00		
(\$\$)	19,437.50	3,500.00	15,937.50	81.99
+ GST 7.00/7.00% (\$\$)	1,360.63	245.00	1,115.63	81.99
Nett Amount (\$\$)	20,798.13	3,745.00	17,053.13	81.99

INSPECTION

Date of Assignment: 23/02/2022

Date Inspected: 23/02/2022 Inspected At: 56 LOYANG WAY,
#04-04 LOYANG ENTERPRISE BUILDING
SINGAPORE 508775
REPAIRER : AP AUTOMOTIVE SERVICES PTE LTD

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jun 2022)
Parts:	213	TOYOTA HIACE 2.8 D GL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for CB8256E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP	Cut	489.00 FL	*360.20 FL
2	1		*TAIL LAMP LOWER GARNISH LH	Repair	125.00 FL	*- FL
3	1		*TAIL LAMP LOWER GARNISH RETAINER LH	Not Necessary	75.00 FL	*- FL
4	1		*REAR BUMPER	Torn	657.00 FL	*545.10 FL
5	1		*REAR BUMPER SIDE RETAINER	Cracked	121.00 FL	*65.00 FL
6	1		*REAR FENDER LH	Repair	2,145.00 FL	*- FL
7	1		*REAR FENDER INNER PANEL LH	Not Necessary	1,568.00 FL	*- FL
8	1		*REAR FENDER GLASS	Broken	698.00 FL	*698.00 FL
9	1		*SLIDING DOOR LH	Repair	1,916.00 FL	*- FL
10	1		*SLIDING DOOR RAILING LH	Not Necessary	652.00 FL	*- FL
11	1		*SLIDING DOOR RAILING END COVER LH	Not Necessary	41.00 FL	*- FL
12	1		*SLIDING DOOR GLASS	Not Necessary	785.00 FL	*- FL
13	1		*REAR ABSORBER LH	Not Necessary	544.00 FL	*- FL
14	1		*REAR WHEEL BEARING LH	Not Necessary	790.00 FL	*- FL
15	1		*REAR AXLE BEAM	Not Necessary	3,545.00 FL	*- FL
16	1		*TAIL AMP CLIP (SET)	Necessary	30.00 FS	*10.00 FS
17	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
18	1		*REAR FENDER INNER TRIM CLIP (SET)	Necessary	60.00 FS	*20.00 FS
19	1		*REAR FENDER INNER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
20	1		*SLIDING DOOR GLASS SEALANT	Not Necessary	60.00 FS	*- FS
21	1		*SLIDING DOOR GLASS INNER SEAL	Not Necessary	60.00 FS	*- FS
22	1		*REAR FENDER GLASS INNER SEAL	Not Necessary	50.00 FS	*- FS
23	1		*REAR FENDER GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
24	1		*REAR RIM LH	Dented	800.00 FS	*400.00 FS
25	1		*REAR TYRE LH	Not Necessary	350.00 FS	*- FS
26	1		*REAR FENDER INNER TRIM BOARD LH	Deformed	579.00 FL	*355.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,360.00	2,493.40
- List Item Discount on L Items 25.00/25.00% (\$)	3,682.50	505.85
Total Parts (\$)	12,677.50	1,987.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS.	New	1,800.00	1,200.00
2	SPRAY PAINTING ON AFFECTED AREAS.	New	1,200.00	800.00
3	TO CHECK LIGHTING AND WIRING.	New	60.00	30.00
4	CONDUCT WATER LEAK TEST.	New	100.00	40.00
5	REMOVE AND REFIT REAR FENDER GLASS.	New	1,500.00	120.00
6	REMOVE AND REFIT REAR RACK TO FACILITATE REPAIR.	New	600.00	0.00
7	REMOVE AND REFIT SLIDING DOOR GLASS.	New	150.00	0.00
8	REMOVE AND REFIT REAR REVERSE SENSOR.	New	200.00	30.00
9	REMOVE AND REFIT CARPET, INTERIOR TRIMS.	New	400.00	100.00
10	REMOVE AND REFIT UNDER CARRIAGE.	New	600.00	0.00
11	TO CONDUCT 4 WHEEL ALIGNMENT.	New	150.00	80.00
Gross Labour Cost (\$\$)			6,760.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >