

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB22001756/VTF3N2**Date:** 28/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SFH1232C **Insured Vehicle No :** SLS8085K

Date of Loss: 22/02/2022 Nature of Claim: TP Claim No: MFL2022D0000839

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFH1232C**
 Make & Model: HONDA STREAM, 1.7 (A) Engine No: R18A13800156
 Reg. Date: 06/03/2009 (Man. Year: 2008) Chassis No: JHMRN68609S200156
 Colour: Blue Odometer: 221237 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65R15 Rear Tyre Size: 205/65R15
 Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
 Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,099.40	7,243.20	4,856.20	40.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	2,630.00	1,470.00	35.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,199.40	9,873.20	6,326.20	39.05
Approved Total (Overridden) (S\$)		7,900.00		
Nett Amount (S\$)	16,199.40	7,900.00	8,299.40	51.23

INSPECTION

Date of Assignment: 23/02/2022

Date Inspected: 24/02/2022 Inspected At: Hs Automotives Pte Ltd (HQ)
 BLK 2 KAKI BUKIT AVE 2, #02-25
 Singapore 417921

Estimated Period of Repair: 8.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Mar 2022)
Parts:	M1-MPV	HONDA STREAM 1.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFH1232C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	638.90 F	*638.90 FL
2	2		*FRONT BONNET HINGE L/R	Serviceable	134.40 F	*- FL
3	1		*FRONT BONNET HEAT SHIELD	Serviceable	94.40 F	*- FL
4	1		*FRONT BONNET RUBBER GARNISH	Serviceable	39.20 F	*- FL
5	1		*LH FRONT FENDER	Dented	519.30 F	*497.50 FL
6	1		*LH FRONT FENDER INNER SHIELD	Cut	91.00 F	*91.00 FL
7	1		*LH WIPER GARNISH	Serviceable	47.00 F	*- FL
8	1		*LH FRONT HEAD LAMP	Cracked	680.40 F	*615.30 FL
9	1		*LH FRONT HEAD LAMP LOWER BRACKET	Cut	37.00 F	*37.00 FL
10	1		*FRONT RADIATOR GRILLE (BLACK BASE)	Scratched	240.60 F	*240.60 FL
11	1		*FRONT RADIATOR GRILLE (CHROME)	Scratched	127.20 F	*127.20 FL
12	1		*FRONT RADIATOR GRILLE LOGO (H)(NPA)	Serviceable	0.00 F	*- FL
13	1		*FRONT BUMPER	Cut	635.60 F	*635.60 FL
14	1		*FRONT BUMPER LOWER GRILLE	Cut	87.00 F	*87.00 FL
15	2		*FRONT BUMPER SIDE RETAINER	Necessary	24.50 F	*24.50 FL
16	1		*REAR TAIL GATE	Dented	903.00 F	*903.00 FL
17	1		*REAR TAIL GATE LOGO (STREAM)	Necessary	31.60 F	*31.60 FL
18	1		*REAR TAIL GATE LOCK	Not Necessary	109.40 F	*- FL
19	1		*REAR TAIL GATE INNER BOARD	Cut	141.00 F	*141.00 FL
20	1		*REAR TAIL GATE WEATHER STRIP	Deformed	121.60 F	*121.60 FL
21	2		*REAR TAIL GATE DAMPER	Serviceable	233.40 F	*- FL
22	1		*REAR TAIL GATE OUTER GARNISH	Repair	162.80 F	*- FL
23	2		*REAR TAIL GATE NO PLATE LAMP	Serviceable	76.00 F	*- FL
24	1		*LH TAIL LAMP	Scratched	352.50 F	*352.50 FL
25	1		*LH TAIL LAMP LOWER BRACKET (NPA)	Not Necessary	0.00 F	*- FL
26	1		*REAR BUMPER	Dented	588.90 F	*588.90 FL
27	1		*REAR BUMPER TOWING COVER	Missing	13.50 F	*13.50 FL
28	2		*REAR BUMPER SIDE RETAINER	Necessary	38.00 F	*38.00 FL
29	1		*REAR END PANEL (OUTER)	Dented	461.70 F	*461.70 FL
30	1		*REAR END PANEL (INNER)(NPA)	Not Necessary	0.00 F	*- FL
31	1		*FRONT BUMPER FOG LAMP COVER	Scratched	22.90 F	*22.90 FL
32	1		*FRONT BUMPER REINFORCEMENT	Dented	218.80 F	*218.80 FL
33	1		*FRONT SUPPORT PANEL	Dented	493.30 F	*493.30 FL
34	1		*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	51.90 F	*- FL
35	1		*FRONT BONNET HEAT SHIELD CLIP	Necessary	45.00 FS	*20.00 FS
36	1		*LH FRONT FENDER INNER SHIELD CLIP	Necessary	45.00 FS	*20.00 FS
37	1		*FRONT RADIATOR GRILLE CLIP	Necessary	45.00 FS	*20.00 FS
38	1		*FRONT BUMPER CLIP	Necessary	45.00 FS	*20.00 FS
39	1		*REAR TAIL GATE INNER BOARD CLIP	Necessary	46.00 FS	*20.00 FS
40	1		*REAR BUMPER CLIP	Necessary	46.00 FS	*20.00 FS
41	4		*REAR BUMPER REVERSE SENSOR	Cut	360.00 FS	*200.00 FS
42	1		*RADIATOR ASSY	Bent	1,365.10 F	*1,365.10 FL
43	1		*AIR COND CONDENSER	Bent	882.50 F	*882.50 FL
44	1		*FRONT SUPPORT PANEL TOP GARNISH CLIP	Necessary	46.00 FS	*20.00 FS
45	1		*LH FRONT DOOR	Repair	1,757.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	12,099.40	8,969.00
				- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,725.80
				Total Parts (S\$)	12,099.40	7,243.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT	New	1,800.00	1,200.00
2	SPRAY PAINT	New	1,800.00	1,200.00
3	TO REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO CHECK WIRING	New	100.00	30.00
5	TO RUST PROOF	New	150.00	50.00
6	TO INSTALL REVERSE SENSOR	New	100.00	30.00
Gross Labour Cost (S\$)			4,100.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >