

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 60986**
Date Estimated : **22/02/2022**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Dawn Lim Sock Kiang
6 Sinaran Drive

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 307468

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMM955Y	WBACR62040LS15	24/06/2019	X5 xDrive40i	43253

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper, bonnet, front air duct and to make good left front fender	3,400.00	0.00	3,400.00
To respray front bumper, bonnet and left front fender	2,107.00	0.00	2,107.00
To carry out body cavity preservation. (Per panel).	112.00	0.00	112.00
To replace left headlight.	457.00	0.00	457.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168.00	0.00	168.00
To check electrical wiring system at the front section for proper function including adjustment of headlights.	168.00	0.00	168.00
To supply front emboss number plate.	83.00	0.00	83.00
Sundries.	150.00	0.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BLIND RIVET	1.20	12.00	0.00	14.40
HOOD	2,240.95	1.00	0.00	2,240.95
FRT SUPPORT	867.75	1.00	0.00	867.75
GRILLE AIR INLET MIDDLE (M)	97.50	1.00	0.00	97.50
LH GRILLE SIDE OPEN (M)	111.05	1.00	0.00	111.05
IMPACT ABSORBER TOP (M)	91.30	1.00	0.00	91.30
FRT NUMBER PLATE CARRIER (M)	73.40	1.00	0.00	73.40
LH AIR INLET FINISHER (M)	124.05	1.00	0.00	124.05
LH AIR CURTAIN (M)	52.05	1.00	0.00	52.05
LH FLAP TOWING LUG PAINTED (SCHWARZ	82.20	1.00	0.00	82.20
FRT BUMPER PANEL PRIMED (M)	1,943.05	1.00	0.00	1,943.05
FRT BUMPER TRIM PAINTED	315.15	1.00	0.00	315.15
# LH FOG LAMP COVER TRIM (M)	236.30	1.00	0.00	236.30
# ADJUSTMENT ELEMENT	7.10	1.00	0.00	7.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

FRT GRILLE	343.95	1.00	0.00	343.95
EMBLEM GROMMET	0.95	2.00	0.00	1.90
PLAQUE 82MM	72.85	1.00	0.00	72.85
EMBLEM M	47.35	1.00	0.00	47.35
AIR DUCT BOTTOM	114.55	1.00	0.00	114.55
AIR FLAPS TOP	315.95	1.00	0.00	315.95
AIR DUCT RADIATOR BOTTOM	68.35	1.00	0.00	68.35
FRT LH BRAKE AIR DUCT	52.05	1.00	0.00	52.05
SET OF CABLES FRT BUMPER	234.40	1.00	0.00	234.40
LH HEADLIGHT LED TECHNOLOGY	4,727.25	1.00	0.00	4,727.25

SUPPLEMENTARY ITEMS

Total Labour :	6,645.00
Total Parts :	12,234.85
Total Labour & Parts :	18,879.85
Deduction for Excess :	
Total Repair Costs less Excess:	18,879.85
GST @7%:	1,321.59
Grand Total :	20,201.44

LOSS OF USE=\$120X 9
GIA SEARCH FEE=\$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 60986**
Date Estimated : **22/02/2022**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Dawn Lim Sock Kiang
6 Sinaran Drive

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 307468

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMM955Y	WBACR62040LS15	24/06/2019	X5 xDrive40i	43253

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# LH FOG LAMP COVER TRIM (M)	236.30	1.00	0.00	236.30	✓ CVT
# ADJUSTMENT ELEMENT	7.10	1.00	0.00	7.10	✓ nec
# SET OF CABLES FRT BUMPER	234.40	1.00	0.00	234.40	✓ TN

SUPPLEMENTARY ITEMS

Total Labour :

Total Parts : 477.80