

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001759/UQY3N2**Date:** 18/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00026992200

Claimant Vehicle No : SJH1735X **Insured Vehicle No :** SMC6290U

Date of Loss: 19/02/2022 Nature of Claim: TP Claim No: SNM22D201328/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH1735X**

Make & Model: HONDA HR-V, 1.5 (A) Engine No: L15B4533922

Reg. Date: 18/06/2018 (Man. Year: 2018) Chassis No: JHMRU1830GX203924

Colour: White Odometer: 62034 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,551.49	804.42	747.07	48.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,460.00	1,870.00	2,590.00	58.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,011.49	2,674.42	3,337.07	55.51
+ GST 7.00/7.00% (\$\$)	420.80	187.21	233.59	55.51
Nett Amount (\$\$)	6,432.29	2,861.63	3,570.66	55.51

INSPECTION

Date of Assignment: 23/02/2022

Date Inspected: 01/03/2022 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Apr 2022)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH1735X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL COMP,R.RR DOOR	Repair	701.32 FS	*- FS
2	1		*TAPER,RR DOOR SASH	Not Necessary	15.75 FS	*- FS
3	1		*TAPE.R.RR DOOR PROTECTION	Scratched/Necessary	19.27 FS	*19.27 FS
4	1		*PROTECTORR.RR WHEEL ARCH	Cut	140.40 FS	*140.40 FS
5	1		*DISK.ALUMINIUM WHEEL	Cut	624.75 FS	*624.75 FS
6	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	1,551.49	804.42
---------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT & PERFORM WATER TEST	New	180.00	0.00
2	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	0.00
3	REMOVE & TRANSFER ITEMS TO NEW RR R DR.ADJUST	New	550.00	0.00
4	STRAIGHTEN ALIGN RR R FENDER	New	1,500.00	650.00
5	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (2P)	New	1,600.00	1,040.00
6	WHEEL ALIGNMENT X4	New	180.00	180.00
Gross Labour Cost (\$)			4,460.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >